original

P-00454

NOAA FORM 76-35

U.S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SURVEY

DESCRIPTIVE REPORT

Type of Survey Coastal Boundary

Job No. PH-7119 *Map No.* TP-00454

Classification No. Final *Edition No.* ...)

Field Edited Map

LOCALITY

State Florida

General Locality Monroe County

Locality Tavernier Key to Treasure Harbor

1972 TO 1975

REGISTRY IN ARCHIVES

DATE

☆ U.S. GOVERNMENT PRINTING OFFICE: 1974-762-901

TP-00454

NOAA FORM 76-36A (3-72) — U. S. DEPARTMENT OF COMMERCE, NATIONAL OCEANIC AND ATMOSPHERIC ADMIN.

DESCRIPTIVE REPORT - DATA RECORD

TYPE OF SURVEY: ☒ ORIGINAL ☐ RESURVEY ☐ REVISED

SURVEY TP. 00454

MAP EDITION NO. (1)

MAP CLASS Final

JOB PH. 7119

PHOTOGRAMMETRIC OFFICE: Rockville, Maryland

OFFICER-IN-CHARGE: Commander James Collins

LAST PRECEEDING MAP EDITION

TYPE OF SURVEY: ☐ ORIGINAL ☐ RESURVEY ☐ REVISED

JOB PH. ____

MAP CLASS ____

SURVEY DATES: 19__ TO 19__

I. INSTRUCTIONS DATED

1. OFFICE	2. FIELD
General Instructions-OFFICE-NOS Cooperative Coastal Boundary Mapping, Job PH-7000, 12/9/75 Supplement I, 11/4/74 Supplement III, 10/24/74 NOTE: Office and field edit instructions(1975) incorporate applicable prior operational instructions.	Aerial photography 9/2/69 Supplement I, 1/28/70 Supplement II, 3/26/70 Supplement III, 8/10/72 Field Edit (PH-7000 General Instructions for Florida Coastal Zone Mapping)1973

II. DATUMS

1. HORIZONTAL: ☒ 1927 NORTH AMERICAN — OTHER (Specify)

2. VERTICAL: ☒ MEAN HIGH-WATER ☒ MEAN LOW-WATER ☐ MEAN LOWER LOW-WATER ☐ MEAN SEA LEVEL — OTHER (Specify): Mean water level

3. MAP PROJECTION: Transverse Mercator

4. GRID(S): STATE: Florida; ZONE: East

5. SCALE: 1:10,000 — STATE: ; ZONE:

III. HISTORY OF OFFICE OPERATIONS

OPERATIONS		NAME	DATE
1. AEROTRIANGULATION METHOD: Analytic	BY	V. McNeel	6/74
	LANDMARKS AND AIDS BY	Inapplicable	
2. CONTROL AND BRIDGE POINTS METHOD: Coradomat	PLOTTED BY	R. Robertson	4/75
	CHECKED BY	Inapplicable	
3. STEREOSCOPIC INSTRUMENT COMPILATION	PLANIMETRY BY	Inapplicable	
	CHECKED BY		
INSTRUMENT:	CONTOURS BY	Inapplicable	
SCALE:	CHECKED BY		
4. MANUSCRIPT DELINEATION	PLANIMETRY BY	P. Gibson	6/75
	CHECKED BY	P. Dempsey	6/75
METHOD: Graphic	CONTOURS BY	Inapplicable	
	CHECKED BY		
	HYDRO SUPPORT DATA BY	Inapplicable	
SCALE: 1:10,000	CHECKED BY		
5. OFFICE INSPECTION PRIOR TO FIELD EDIT	BY	J. Battley, Jr.	7/65
6. APPLICATION OF FIELD EDIT DATA	BY	J. McClure	10/75
	CHECKED BY	J. Battley, Jr.	12/75
7. COMPILATION SECTION REVIEW	BY	P. Dempsey	1/76
8. FINAL REVIEW	BY	D. Brant	2/76
9. DATA FORWARDED TO PHOTOGRAMMETRIC BRANCH	BY		
10. DATA EXAMINED IN PHOTOGRAMMETRIC BRANCH	BY	D. Brant	5/76
11. MAP REGISTERED - COASTAL SURVEY SECTION	BY	R. J. CATOK	9/76

NOAA FORM 76-36A — SUPERSEDES FORM C&GS 181 SERIES

* U.S. G.P.O. 1972-769382/582 REG.#6

[redacted]

TP-00454

[redacted]

NOAA FORM 76-36B(1)
(7-75)

U. S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SURVEY

TIDE - COORDINATED PHOTOGRAPHY

TP _ 00454

LOCATION AND PHOTOGRAPHY	TIDE STATIONS *(In operation at time of photography)*	STAGE OF TIDE	MEAN RANGE
			at tide station
ATLANTIC OCEAN			
72K6501R-6503R	Tavernier, Hawk Channel	+0.10 MHW	2.13'
72K6379R-6382R	Tavernier, Hawk Channel	+0.13 MLW	
FLORIDA BAY			
72K6501R-6503R	Tavernier, Florida Bay	+0.20 MWL	- -
72K6379R-6382R	Tavernier, Florida Bay	+0.16 MWL	- -

REMARKS: The periodic tide on TP-00454 (Florida Bay) was masked by nontidal forces and the mean range was substantially less than two-tenths of a foot. In this situation the mean high/low water datums converge, and for mapping purposes, the mean high and low water lines are indistinguisable. As a consequence, special treatment was given to the portrayal of the shoreline on this map: the mean water leven line was mapped in lieu of the mean high water line and shown by a distinative symbol.

NOAA FORM 76-36C
(3-72)

U. S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SURVEY

TP-00454

HISTORY OF FIELD OPERATIONS

I. [X] FIELD INSPECTION OPERATION * Feb. Mar. 1972 [X] FIELD EDIT OPERATION Aug. 1975

OPERATION		NAME	DATE
1. CHIEF OF FIELD PARTY		R.R. Wagner	
2. HORIZONTAL CONTROL	RECOVERED BY	R.R. Wagner	8/75
	ESTABLISHED BY		
	PRE-MARKED OR IDENTIFIED BY		
3. VERTICAL CONTROL	RECOVERED BY	R.R. Wagner	8/75
	ESTABLISHED BY		
	~~PRE-MARKED OR~~ IDENTIFIED BY	R.R. Wagner	8/75
4. LANDMARKS AND AIDS TO NAVIGATION	RECOVERED *(Triangulation Stations)* BY	R.R. Wagner	8/75
	LOCATED *(Field Methods)* BY	R.R. Wagner	8/75
	IDENTIFIED BY		
5. GEOGRAPHIC NAMES INVESTIGATION	TYPE OF INVESTIGATION: [ ] COMPLETE [ ] SPECIFIC NAMES ONLY [X] NO INVESTIGATION — BY		
6. PHOTO INSPECTION	CLARIFICATION OF DETAILS BY	R.R. Wagner	8/75
7. BOUNDARIES AND LIMITS	SURVEYED OR IDENTIFIED BY	N.A.	

II. SOURCE DATA

1. HORIZONTAL CONTROL IDENTIFIED

2. VERTICAL CONTROL IDENTIFIED

PHOTO NUMBER	STATION NAME	PHOTO NUMBER	STATION DESIGNATION
	Refer to Field Report	73L2795R 73L2796R	G276 J276, K276

3. PHOTO NUMBERS *(Clarification of details)*

73L2795R; 2796R

4. LANDMARKS AND AIDS TO NAVIGATION IDENTIFIED

Landmarks and nonfloating aids were either verified or located during field edit.

PHOTO NUMBER	OBJECT NAME	PHOTO NUMBER	OBJECT NAME

5. GEOGRAPHIC NAMES: [ ] REPORT [XX] NONE

6. BOUNDARY AND LIMITS: [ ] REPORT [XX] NONE

7. SUPPLEMENTAL MAPS AND PLANS

8. OTHER FIELD RECORDS *(Sketch books, etc.* **DO NOT** *list data submitted to the Geodesy Division)*

4 pages of sextant cuts

*Refer to Field Reports bound with this Descriptive Report.

NOAA FORM 76-36C
(3-72)

* U.S. G.P.O. 1972-769381/567 REG.#6

NOAA FORM 76-36D
(3-72)

U. S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION

RECORD OF SURVEY USE

TP-00454

I. MANUSCRIPT COPIES

COMPILATION STAGES			DATE MANUSCRIPT FORWARDED	
DATA COMPILED	DATE	REMARKS	MARINE CHARTS	HYDRO SUPPORT
No map copies were furnished to Nautical Charts prior to final review.				
			9/9/76	

II. LANDMARKS AND AIDS TO NAVIGATION

1. REPORTS TO MARINE CHART DIVISION, NAUTICAL DATA BRANCH

NUMBER	CHART LETTER NUMBER ASSIGNED	DATE FORWARDED	REMARKS
		10/20/75	Two forms 76-40(listings) submitted as
			final report.

2. [X] REPORT TO MARINE CHART DIVISION, COAST PILOT BRANCH. DATE FORWARDED: 10/20/76
3. [ ] REPORT TO AERONAUTICAL CHART DIVISION, AERONAUTICAL DATA SECTION. DATE FORWARDED: _____

III. FEDERAL RECORDS CENTER DATA

1. [✓] BRIDGING PHOTOGRAPHS; [✓] DUPLICATE BRIDGING REPORT; [✓] COMPUTER READOUTS.
2. [✓] CONTROL STATION IDENTIFICATION CARDS; [✓] FORM NOS 567 SUBMITTED BY FIELD PARTIES.
3. [✓] SOURCE DATA *(except for Geographic Names Report)* AS LISTED IN SECTION II, NOAA FORM 76-36C. ACCOUNT FOR EXCEPTIONS:

4. [ ] DATA TO FEDERAL RECORDS CENTER. DATE FORWARDED: _____

IV. SURVEY EDITIONS *(This section shall be completed each time a new map edition is registered)*

	SURVEY NUMBER	JOB NUMBER	TYPE OF SURVEY / MAP CLASS
SECOND EDITION	TP - _____ (2)	PH - _____	☐ REVISED ☐ RESURVEY ☐ II. ☐ III. ☐ IV. ☐ V. ☐ FINAL
	DATE OF PHOTOGRAPHY	DATE OF FIELD EDIT	
THIRD EDITION	SURVEY NUMBER TP - _____ (3)	JOB NUMBER PH- _____	TYPE OF SURVEY ☐ REVISED ☐ RESURVEY MAP CLASS ☐ II. ☐ III. ☐ IV. ☐ V. ☐ FINAL
	DATE OF PHOTOGRAPHY	DATE OF FIELD EDIT	
FOURTH EDITION	SURVEY NUMBER TP - _____ (4)	JOB NUMBER PH - _____	TYPE OF SURVEY ☐ REVISED ☐ RESURVEY MAP CLASS ☐ II. ☐ III. ☐ IV. ☐ V. ☐ FINAL
	DATE OF PHOTOGRAPHY	DATE OF FIELD EDIT	

☆U. S. GOVERNMENT PRINTING OFFICE: 1973--778075/1077 REGION NO. 6

SUMMARY
for
TP-00444 thru TP-00454

Coastal Zone Map TP- 00454 is one of eleven (11), 1:10,000 scale (shoreline type) maps in Job PH-7119. These maps will not be published. Interior detail is limited to a narrow zone of planimetry usually back to and including the first road.

A layout of Job PH-7119 (revised since the aerotriangulation operation) will show the location of the individual maps. A copy of this layout is included in this Descriptive Report.

The maps are intended for palnning purposes for the State of Florida and for the construction and maintenance of NOS nautical charts.

The area is covered by aerial photography taken in 1972 and 1973 on color and black-and-white infrared film. The infrared film was tide coordinated.

The field operations consisted of the following:

1. Premarking of horizontal control for aerotriangulation.
2. Establishment of tidal datums.
3. Field Edit.

Horizontal control was extended by analytical aerotriangulation method using the STK stereocomparator.

The shoreline and alongshore details were compiled from tide-coordinated, black-and-white infrared photography using a B-8 stereoplotter and/or graphic methods. The rectified color photography was used as an aid in interpreting cultural features and compiling the limits of vegetation. The interior details were compiled from a stereoscopic examination of the color photography without field edit.

All line work is scribed, approved symbols are shown in the marginal data of the map.

A registration copy of each map is prepared. The registration copy shows additional offshore details such as shoal and

shallow lines used by the Marine Chart Division but not required on the Coastal Zone Maps. This copy of the map is labeled "Registration Copy" in the title block.

The following items will be registered in the NOS Archives:

1. A stable base copy of the Registration Copy.

2. The Descriptive Report.

All negatives are filed in the Reproduction Division.

Field records such as field edit sheets, discrepancy prints, field edit photographs, and other field records are filed in the National Archives.



Official Mileage for Cost Accounts

Sheet No.	Sq. Miles
TP-00444	2
TP-00445	8
TP-00446	6
TP-00447	10
TP-00448	8
TP-00449	2
TP-00450	8
TP-00451	4
TP-00452	4
TP-00453	6
TP-00454	5
Total	63

JOB PH-7119

CARD SOUND to PLANTATION KEY

FLORIDA

SHORELINE MAPPING

SCALE 1:10000

REVISED 12/9/75 RWW

FIELD REPORT

JOB PH-7119

This report is on work done in accordance with Instructions-field-Job PH-7119; Horizontal Control for Aerotriangulation and Field Support for Aerial Photography; Coastal Boundary Mapping, Card Sound to Plantation Key, Florida. The field work was done during the period 20 July - 7 September 1971.

1. PREMARKING OF CONTROL

One control station, IRVING 1971, was established on Soldier Key. Eighteen stations were paneled for 1:30,000 scale photography. The deviations from the job diagram and target specifications were recommended in the field by Mr. Saperstein, Photogrammetrist and authorized by the Chief, Surveys Planning Branch. The locations of the paneled stations are shown on the chart section accompanying this report.

2. BRIDGING PHOTOGRAPHY

Flight lines are shown on the accompanying chart. Bridging photography was accomplished on March 8, 1971 for lines 30-4, 30-5, and 30-6 under Job PH-7113. Line 30-6 was redesignated 30-1 for Job PH-7119. Line 20-1 was photographed on Aug. 4 and all other lines on Aug. 11 - the only suitable day in the period 4-26 August. This photography was unacceptable and will be rescheduled for February 1972.

3. TIDE-COORDINATED PHOTOGRAPHY

Locations of the tide staffs are shown on the accompanying chart. Lines 30-4 and 30-5 carried over from Job PH-7113 were completed. Lines 20-2 and 30-3 (Outside) were also completed. Clouds throughout the period prevented completing all lines and the job except for 30-4 and 30-5 will be rescheduled for February 1972. The times are summarized below in case the pictures will be used to supplement the future February work.

Recordings entered in the tide volumes, Form 277, were at 5 minute intervals during photography and at 15 minute intervals near photography. Tolerances of ±0.3 ft. for MHW and ±0.1 ft. for MLW were observed. Wet staff readings - crest, mean, and trough - were recorded while photography was in progress. Eastern Standard Time was used.

Line 30-4. Flown for MHW on March 2, 1971 at 1319-1325 when both MIAMI BISCAYNE BAY and CUTLER were in range. The north end

was flown for MLW at 1325-1335 on August 6 when the MIAMI BISCAYNE BAY staff read 2.3 and 2.2. The south end was flown for MLW at 1425-1435 on August 6 when the CUTLER staff read 2.75 and 2.69.

Line 30-5. MHW North half flown at 805-815 on August 7 when CUTLER staff read 4.5 to 4.7. South half flown at 1220-1235 on August 7 when the TURKEY POINT staff read 3.15 to 3.05. MLW North half was flown at 1430-1435 on 6 August when the CUTLER staff read 2.73 to 2.69. South half flown at 850-855 on August 11 when the TURKEY POINT staff read 1.65. This was flown at a reduced altitude of 14,000 feet to get under some clouds. A triplicate was flown at 855-900 to get outlying islands which might not have been covered at the reduced altitude.

Line 20-2. MHW The northern two-thirds were flown at 802-815 on August 9 when the OCEAN REEF staff read 4.58 to 4.70. The remainder was flown at 830-840 on August 10 when the staff read 4.25 to 4.35. MLW Due to clouds this was flown in three parts. The NE end to the Ocean Reef Club was flown at 1328-1342 on August 7 when the staff read 2.25 to 2.11, the Ne end was flown at 1530 on August 6 when the staff read 2.2, and the south part flown at 955-1001 on 16 August when the staff read 2.30.

Line 30-3 (Outside) MHW Flown at 939-947 on August 11 when the TAVERNIER HAWK CHANNEL staff read 4.00 to 4.12. MLW Flown at 1315-1322 on August 4 when the staff read 2.1.

Line 30-3 (Inside) No photography. Clouds and seasonal high tides during the rest of the period prevented it.

Line 20-1. MHW No photography. MLW Line was flown at 927-945 on August 16 when the RAGGED KEYS staff read 1.8 to 1.75.

Line 30-1. MHW The middle third was flown at 1020-1025 on August 4 when the CARD SOUND staff read 3.7 and the MANATEE CREEK staff read 3.5. The remainder was flown at 1110-1115 the same day when the CARD SOUND staff read 3.6 and the MANATEE CREEK staff read 3.5. MLW No photography.

Line 30-2. Line was flown at 835-842 on August 9 when the CARD Sound staff read 3.6 and the MANATEE CREEK staff read 3.75. Line was unacceptable because of clouds in the middle segment and possible smoke in the northern third. This and the MLW photography were not accomplished due to clouds and seasonal high water.

4. ADDITIONAL PHOTOGRAPHY

Tide coordinated photography was taken on a small shoal about one

mile NNE of the Molasses Reef light. The shoal was photographed at about 0900 on August 10 when the TAVERNIER HAWK CHANNEL staff was in MHW range. It was flown at 1206 on August 16 when the staff read 2.31. This shoal was also photographed in color and false color, but the times were not obtained from the photographer.

5. FORESHORE PROFILES

Four planetable beach profiles were run within the limits of the job by Mr. Dale Fuller during the photography period. A brief report accompanies the profile sheet.

6. FIELD RECORDS

All CSI cards, recovery notes, profiles and the original field records for IRVING 1971 were forwarded to C3413 on 1 March 1972. Form 277, Tides Volumes for the MIAMI BISCAYNE BAY, TURKEY POINT, and CUTLER Tide staffs were also forwarded on 1 March. The 277's for the other staffs will be forwarded with the report for the February 1972 photography.

Submitted 29 February 1972

John C. Veselenak

John C. Veselenak
Chief, Photo Party 65

FIELD REPORT

JOB PH-7119

This report is on work done in accordance with Instructions-Field-Job PH-7119; Horizontal Control for Aerotriangulation and Field Support for Aerial Photography; Coastal Boundary Mapping, Card Sound to Plantation Key, Florida, dated January 31, 1972. The field work was done during the period 7-23 February 1972.

1. PREMARKING OF CONTROL

Four stations were paneled for 1:30,000 scale photography. The locations are shown on the chart section accompanying this report.

2. AEROTRIANGULATION PHOTOGRAPHY

Flight lines are shown on the chart. Color photography was accomplished on February 19, 1972 between the approximate times of 1045 and 1230 hours. The skies were exceptionally clear for this area and the ground winds was from the northwest at 20-25 knots all morning. These lines were also flown on February 14, but the photography was unacceptable because of a bad film emulsion.

3. TIDE-COORDINATED PHOTOGRAPHY

Locations of the tide staffs are shown on the chart. The job was completed; photography taken on the 12, 14, 15, 16, and 20, of February. Lines 20-2 and 30-3 were also photographed and portions of the other lines were also partially photographed during August 1971.

Recordings entered in the tide volumes, Form 277, were at 5 minute intervals during photography and at 15 minute intervals near photography. An exception to this is the readings for the MANATEE CREEK and BARNES SOUND staff where the tide varies only a few hundredths of a foot per day. Tolerances of ±0.30 foot for MHW, ±0.20 foot for MWL, and ±0.10 foot for MLW were observed. Wet staff readings - crest, mean, and trough - were recorded while photography was in progress. Eastern Standard Time was used.

Line 20-1. MHW Completed at 1050 on February 14 when the RAGGED KEYS staff read 3.38-3.26. MLW Completed at 1500 on February 14 when the staff read 1.80.

Line 30-2. MHW Flown at 1035-1052 on 16 February when the OCEAN REEF staff read 4.75-4.61. This line was also flown at 1006 on February 15, but the pilot recommended it be rescheduled. MLW Flown at 1338-1350 on February 14 when the staff read 2.31-2.32.

Line 30-1. This line is controlled by three staffs, the MANATEE CREEK staff has a MWL datum and the EAST ARSENICKER and CARD SOUND staffs have mean high and mean low datums. MHW The line was flown at 1120-1142 on 14 February. At this time the EAST ARSENICKER staff read 3.95-3.86 and the MANATEE CREEK staff read 3.54-3.57(MWL). The line was flown again at 1445 on 14 February when the CARD SOUND staff read 3.8 and the MANATEE CREEK staff read 3.60. MLW Was flown at 945-1000 on 20 February when the CARD SOUND staff read 3.2 and the EAST ARSENICKER staff read 2.78-2.81.

Line 30-2. MHW It was completed at 1250 on February 14 when the TAVERNIER, FLA. BAY staff read 3.05 (MWL Range), the BARNES SOUND staff read 3.92, the MANATEE CREEK staff read between 3.6 and 3.5, the CARD SOUND staff read 4.0 and the EAST ARSENICKER staff read 3.65. MLW Completed at 0945 on February 20 when the CARD SOUND staff read 3.20 and the EAST Arsenicker staff read 2.77-2.78.

The BARNES SOUND staff read 0.31 foot higher than its 3.61 Mean Water Level. Since the shoreline in this area is overhung with mangrove this section of the line was not rescheduled.

Line 30-3 (ATLANTIC SIDE). MHW Completed at 1107 on February 16 when the TAVERNIER, HAWK CHANNEL staff read 4.62-4.43. MLW Completed at 1412 on February 14 when the staff read 2.30-2.28.

Line 30-3 (Florida Bay Side). MWL The north side was completed on February 12 at 1150 hrs. when the BARNES SOUND staff read 3.78 and the TAVERNIER, FLA. BAY staff read 2.72. The south end was in range at 1412 on February 14 when 30-3(ATLANTIC SIDE) MLW was flown. The south half was also in range at 1107 on February 16 when 30-3 MHW was flown although the staff was not manned at that time.

4. ADDITIONAL PHOTOGRAPHY

Special photography over Florida's test area was flown between 1005 and 1240 on 20 February with various films. The staff at the EAST ARSENICKER gage was observed and its value recorded at 5 minute intervals during this period. The staff at the

mouth of the northern cut (MANGROVE POINT) was observed and its value recorded at 5 minute intervals from 1135 to 1300 hours. The latter staff values are listed in the EAST ARSENICKER Form 277.

5. FORESHORE PROFILES

Four planetable beach profiles were run within the limits of the job during the photography period of August 1971. The few small beaches found for the profiles were of coral, and since erosion is not considered a problem, these profiles were not rerun.

6. MONITORING OF TEMPORARY TIDE STAFFS IN THE JOB AREA

On February 15 verbal instructions were received from the Chief, Tidal Datum Planes: Temporary staffs were to be put in at 11 selected locations and observed every 12, 15, or 30 minutes through one high and one low water. All 11 need not be observed simultaneously and the actual location could be varied slightly. Four were observed on the 16th., two on the 17th., 1 on the 20th., and four on the 21st. The chart accompanying this report shows the exact location of each staff.

7. FIELD RECORDS

All CSI cards, Form 277's and a copy of the records from the 11 tide staffs were sent to C3413 on 13 March 1972. The original field records for the 11 staffs were forwarded to C3311 on 23 February 1972. Profiles and recovery notes were sent to C3413 on 1 March 1972 with the report for work done on this job in August 1971.

Submitted 14 March 1972

John C. Veselenak

John C. Veselenak
Chief, Photo Party 65

Photogrammetric Plot Report
Hillsboro Inlet to Card Sound, Florida
Job PH-7113
and
Card Sound to Plantation Key, Florida
Job PH-7119

21. Area Covered

This report covers an area on the east coast of Florida immediately south of Hillsboro Inlet to the southwestern end of Plantation Key. Job PH-7113 and Job PH-7119 are combined in this one report because the southern portion of Job PH-7113 is included in the block adjustment of Job PH-7119.

Job PH-7113 consists of twenty (20) 1:10,000 scale sheets: TP-00416 through TP-00420, and TP-00422 through TP-00436.

Job PH-7119 consists of twelve (12) 1:10,000 scale sheets: TP-00444 through TP-00455.

Subsequent to the initial bridging in this area, three small areas were re-bridged using new photography. The reports are attached:

(1) Port Everglades, Florida
(2) Miami to Mangrove Point, Florida
(3) Hollywood to Miami Beach, Florida

22. Method

Eleven (11) strips of photography were bridged using aerotriangulation methods. Tie points were made between strip No. 1 of PH-7113 and strip No. 2 of the Jupiter Inlet to Hillsboro Inlet, Florida report to the north of this area.

Due to the placement of control in relation to flight lines and due to large areas of water coverage, two block adjustments were made. Strip No. 2, No. 3, and No. 4 comprised one block. Strip No. 7, No. 9, No. 10, and No. 11 comprised the other block. Attached is a sketch showing the location of the strips and the blocks.

Image points were located to rectify photographs for orthophoto, nautical, and small craft charts. All points were drilled by the PUG method. Closure to control has been noted on the read-outs. A sketch is attached which shows the control used in the strip



Ratio points were located on twenty-eight (28) strips of infrared

[redacted]

3

The following control station positions were transferred from photographs 72L(C)8691R thru 72L(C)8698R:

Tavernier 1935
Snake 1934 Sub. Sta.

Turkey Pt. 2, RM2 was transferred from photograph 71E(C)9595.

Cape Florida Old Tower Finial Sub Station A was transferred from photograph 71E(C)9201.

Lower Sound Point 1853 sbu. station was not used in the adjustment because the field party advised that it was questionable and should be used with caution. Sub. station Key Largo Visions, Inc., Taller Mast, 1961, could not be used because one of its azimuth stations (Key Largo Cable Visions, Inc. Shorter Mast) appears to have a bad published position. To date, this has not been resolved by the Geodesy Division. Turkey Point 2, RM2 was a very poor point to transfer, and, therefore, it was not used as control in the block adjustment in that area.

Part-way through the compilation phase of this project, it was determined that the published control positions in the area of this report were in error approximately - 4 feet in X and -10 ft. in Y. Therefore, Strip No. 1, No. 2, No. 3, No.4, No. 5, No. 6, and No. 8 are adjusted to the old published control positions. This area includes T-sheets TP-00416 through TP-00420 and TP-00422 through TP-00432.

Strip No. 7, No. 9, No. 10, and No. 11 are adjusted to new preliminary control positions which were furnished by Geodesy on May 29, 1974. Geodesy Division stated this preliminary control will be within one (1) foot of the final adjustment. They also said to base non-main scheme stations on the nearest main scheme

A listing of closures to control is included on an attached sheet of control stations. The station with the largest residual is Narrow Point 1854, with 1.808 feet in X and 1.267 feet in Y.

24. Supplemental Data

USGS Topographic Quadrangles and NOS Nautical Charts were used to obtain vertical control for bridging.

25. Photography

The following RC-8 color photography was used for bridging:

1:20,000 scale

Strip No. 4 71E(C)9201-9215
Strip No. 8 73L(C)2871-2884R
Strip No. 9 73L(C)2893-2924R

1:30,000 scale

Strip No. 1 71E(C)9120-9135
Strip No. 2 71E(C)9562-9574
Strip No. 3 71E(C)9576-9586
Strip No. 5 71E(C)9536-9545
Strip No. 6 71E(C)9588-9602

1:40,000 scale

Strip No. 7 73L(C)2935-2945R
Strip No. 10 73L(C)2952-2968R
Strip No. 11 73L(C)2785-2797R

The quality and definition of the photography was adequate.

Respectfully submitted,

Victor McNeel

Approved and forwarded:

John D. Perrow, Jr.
Chief, Aerotriangulation Section

CONTROL STATIONS

			residuals	
1.	(027100)	Turtle 1929	-0.706	-0.115
2.	(023102)	Pompano, 1928, subpoint B	1.488	-0.229
3.	(029100)	South Jetty, 1938	-1.134	0.176
4.	(034101)	Halland, 1928	0.317	-0.007
5.	(567101)	Causeway, 1934	0.027	-0.012
6.	(562101)	Point View, 1934	0.000	-0.181
7.	(207100)	Base, 1934	0.112	0.142
8.	(204100)	Key Biscayne North Base, 1849	-0.158	0.033
9.	(201101)	Cape Florida Old Tower Finial, subpoint A	-0.156	0.002
10.	(538102)	Pan American, 1935, Target 2	0.000	0.000
11.	(534101)	Naco 1934, subpoint A	0.000	0.000
12.	(544801)	Tie point from strip #5 used as control for strip#6	-0.157	0.025
13.	(591100)	Black Point 3	0.351	-0.066
14.	(595101)	Turkey Point No. 2, 1930, RM No. 2	-0.229	0.073
15.	(940100) (602100)	Narrow Point 1854	-1.808	1.267
16.	(944100)	Man 1930.	0.222	-0.009
17.	(960100)	Long Sound, 1961	-0.168	-0.075
18.	(936101)	Snipe Point, 1934, substation	-0.215	-0.201
19.	(878101)	Irving, 1971, substation	0.687	-0.080
20.	(875102)	Mangrove (USE), 1930, subpoint B	-0.826	0.125
21.	(872101)	Sands Cut RM 2, 1849-1947		





JOB PH-7113
AND
JOB PH-7119

HILLSBORO INLET
TO
PLANTATION KEY,
FLORIDA

CONTROL STATIONS
USED IN THE
ADJUSTMENTS

30.	(967101)	Low 2, RM 2, 1934	0.042	0.215
31.	(692100)	Tavernier, 1935	0.308	-1.325
32.	(793101)	Planter 2, RM 4	-1.476	1.087
33.	(695101)	Snake, 1934, subpoint	0.128	0.174

** means not used in adjustments



JOB PH-7113
AND
JOB PH-7119

HILLSBORO INLET
TO
PLANTATION KEY,
FLORIDA

INFRA-RED CONTACT
PRINTS RATIOED FOR
COMPILATION

INFRA-RED CONTACT PRINTS

1. 71K 5632R - 5660R MLW
2. 71K 5662R - 5672R MLW
3. 71K 5750R - 5766R MHW



FLORIDA– NOAA Coastal Boundary Mapping Program

Horizontal Control

Map TP– 00454

Station	NOS Geodetic Data Reference for Description, Positions, Coordinates and Azimuths
HEN AND CHICKEN LIGHT 1934	Book 425 P. 9; GP 368 Fla. Vol. 1; PC P. 93 Fla. E. Zone
TAURUS 1857	Book 425 P. 8, 28, 36; GP P. 369 Fla. Vol. 1; PC P. 93 Fla. E. Zone
DUBERRY 1934	Book 425 P. 8, 28, 31; GP P. 368 Fla. Vol. 1; PC P. 93 Fla. E. Zone
SNAKE, 1934	Book, 426, P. 7, 8, 37; GP Fla. Vol 1, P. 362. PC Fla. E. Zone, P. 90

Compilation Report
TP-00454
January 1975

31. Delineation

The tidal datum lines were delineated from tide-coordinated black-and-white infrared photography. This photography was controlled by planimetric features common to the rectified color infrared photography and maps points determined by aerotriangulation. The color infrared photography was used as an aid in the interpretation and delineation of cultural shoreline.

Interior details were compiled from the rectified color infrared photography.

32. Control

Horizontal control was adequate. (See Photogrammetric Plot Report.)

33. Supplemental Data - None

34. Contours and Drainage

Contours are inapplicable. Drainage was compiled from color infrared photography.

35. Shoreline and Alongshore Detail

The tide-coordinated, black-and-white infrared photography was adequate for the delineation of the mean high water line and the mean low water line.

36. Offshore Details

No unusual problems were encountered.

37. Landmarks and Aids

One landmark and three lights were located by aerotriangulation and will be verified by field edit. Other charted landmarks will be located by field methods.

38. Control for Future Surveys - None

39. Junctions

Refer to Form 76-36B(Data Record).

40. Horizontal and Vertical Control

The map complies with the accuracy requirements for the Florida Coastal

A comparison was made with the following USGS Quad:

Plantation Key, Florida 1971 1:24,000

FIELD EDIT REPORT, MAP TP-00454, JOB PH 7119

51. METHODS

The shoreline was inspected from a small boat while cruising just off shore. Notes regarding fast and apparent shoreline, piers and other along shore features will be found on the rectified photographs and the field edit sheet.

Four triangulation stations were recovered.

Three vertical bench marks were recovered and identified.

One radio tower is recommended for charting.

All known aids were located or verified.

Three tide stations were identified. Plantation Key, Atlantic Ocean with Tidal Bench Mark 2, Plantation Key North with Tidal Bench Mark 1 and Plantation Key, Florida Bay with Tidal Bench Mark 1 were identified on 73L2795R.

Field Edit notes will be found on the rectified photographs, discrepancy print and the field edit sheet.

52. ADEQUACY OF COMPILATION

Adequate after application of field edit.

53. MAP ACCURACY

No test required.

54. RECOMMENDATIONS

None

55. EXAMINATION OF PROOF COPY

Not required.

Submitted

Robert R. Wagner
Chief, Photo Party 60

REVIEW REPORT
TP-00454

August 1976

61. General

The map manuscript for Coastal Zone Map TP-00454 was inspected as a Class III map (compilation, discrepancy print, and report) and reviewed as a Class I map by the Quality Control Group. The review consisted of an examination of the map manuscript, the field edit and its application, the reproduction negatives, and the Descriptive Report.

The proof copy of this map was edited by the Qualtiy Control Group before making final copies. This edit compriseda thorough inspection of map details to verify the accuracy of reproduction with reference to the map manuscript and the quality of reproduction. In addition, the proof copy was examined by the following sections:

Coastal Mapping - map details
Staff Geographer - geographic names
Coastal Surveys - horizontal and vertical control

There were no planetable beach profiles available for compilation or final review.

62. Cartographic Comparison

Comparison was made with the following USGS quadrangle map; 1:24,000 scale:

Plantation Key, Florida, 1971

Comparison was made with the following Nautical Chart:

11463 (formerly C&GS 850) 7th Edition, dated August 3, 1974, 1:40,000 scale.

1. Chart 11463 shows an extensive MLW area around Tavernier Key not shown on map TP-00454. This area was investigated during field edit and was compiled from the field editors interpretation of the photography while walking the area.

2. Copies of the Field Editors notes for other areas investigated during field edit are attached to the Chart Maintenance Print.

63. thru 65. Inapplicable.

66. Adequacy of Results and Future Surveys

Coastal Zone Map TP-00454 complies with the Instructions for NOS Cooperative Boundary Mapping, Job PH-7000, and the National Standards of Map Accuracy.

Submitted by:

Donald M. Brant

Approved and Forwarded:

Chief, Photogrammetric Branch

Chief, Coastal Mapping Division

27 Jan. 1975

GEOGRAPHIC NAMES

PH-7119 (Card Sound to Plantation Key, Florida)

TP-00454

Cotton Key Basin

Cowpens Anchorage

Davis Reef

Everglades National Park

Florida Bay

~~Hawk Channel~~ JM

Hen and Chickens

Plantation Key

Plantation Point

Straits of Florida

Tavernier Creek

Tavernier Key

The Rocks

Treasure Harbor

Approved by:

Chas. E. Harrington

Chas. E. Harrington
Staff Geographer-C51x2

76-40 PHOTOGRAMMETRIC BRANCH NATIONAL OCEAN SURVEY NOAA STPL
LISTING COASTAL MAPPING DIVISION DEPARTMENT OF COMMERCE USA VERSION 09/18/75

SVY TP-00454 | RPT UNIT CMD ROCKVILLE, MD. | PAGE 1 OF 2
JOB PH-7119 | NONFLOATING AIDS FOR CHARTS | STATE FLORIDA
PRJ R | TO BE CHARTED | LOCALITY TRAV KEY TO TRES HAR | ORIGINATING ACTIVITY
DTM NA 1927 | | DATE 10/11/75 | COMPILATION

THE FOLLOWING OBJECTS HAVE NOT BEEN INSPECTED FROM SEAWARD TO DETERMINE THEIR VALUE AS LANDMARKS

CHARTING NAME	DESCRIPTION RECORD REASON FOR DELETION PUT TRIANGULATION NAMES IN ( )	POSITION LATITUDE LONGITUDE	DM DP	CODES C-C SEQ	METHOD AND DATE OF LOCATION OFFICE	FIELD	CHARTS AFFECTED
	BISCAYNE BAY- LONG KEY						
DYBN 76	COWPENS	24 59 58.73 80 33 37.83	1807.1 1060.8	219 1		P-L-3-8 08/20/75	11451 11463
DYBN 76A	DITTO	24 59 56.13 80 33 39.34	1727.1 1103.2	219 2		DITTO	DITTO
LIGHT 78	DITTO	24 59 43.95 80 33 55.78	1352.3 1564.2	200 5	73LC2795R 03/05/73	P-V-8	DITTO
	HAWK CHANNEL						
LIGHT 40	HEN AND CHICKENS SHOAL LIGHT	24 55 57.24 80 32 56.10	1761.2 1574.0	NOT DGTZD	73LC2797R 03/05/73	TRIG. REC. 08/21/75	DITTO
LIGHT 2	SNAKE CREEK	24 56 27.54 80 34 52.63	847.4 1476.6	200 6	73LC2797R 03/05/73	P-V-8	DITTO
DYBN 4	DITTO	24 55 31.92 80 34 59.38	982.1 1665.9	219 3		P-L-3-8 08/21/75	DITTO
DYBN 2A	DITTO	24 55 31.17 80 34 58.85	959.1 1651.1	219 4		DITTO	DITTO

TYPE OF ACTION	NAMES OF RESPONSIBLE PERSONNEL	ORIGINATOR
POSITIONS DETERMINED AND/OR VERIFIED BY FIELD AND OFFICE ACTIVITIES	ROBERT R. WAGNER P. DEMPSEY AND VERIFIED BY J. BATTLEY J. PIRRONE J. TAYLOR	FIELD REPRESENTATIVE OFFICE COMPILER DIGITIZER DATA PROCESSER

76-40 PHOTOGRAMMETRIC BRANCH NATIONAL OCEAN SURVEY NOAA STPL
LISTING COASTAL MAPPING DIVISION DEPARTMENT OF COMMERCE USA VERSION 09/18/75

SVY TP-00454		RPT UNIT CMD ROCKVILLE, MD.	PAGE 2 OF 2		
JOB PH-7119	LANDMARKS FOR CHARTS	STATE FLORIDA			
PRJ R	TO BE CHARTED	LOCALITY TRAV KEY TO TRES HAR	ORIGINATING ACTIVITY		
DTM NA 1927		DATE 10/11/75	COMPILATION		

THE FOLLOWING OBJECTS HAVE BEEN INSPECTED FROM SEAWARD TO DETERMINE THEIR VALUE AS LANDMARKS

CHARTING NAME	DESCRIPTION RECORD REASON FOR DELETION PUT TRIANGULATION NAMES IN ( )	POSITION LATITUDE LONGITUDE	DM DP	CODES C-C SEQ	METHOD AND DATE OF LOCATION OFFICE	FIELD	CHARTS AFFECTED
RADIO TOWER	HT 503≥509↑	24 57 33.57 80 34 29.95	1032.9 840.1	86 7		P-V-8	11451 11463

32

TYPE OF ACTION	NAMES OF RESPONSIBLE PERSONNEL	ORIGINATOR
OBJECTS INSPECTED FROM SEAWARD	ROBERT R. WAGNER	PHOTO FIELD PARTY
POSITIONS DETERMINED AND/OR VERIFIED BY FIELD AND OFFICE ACTIVITIES	ROBERT R. WAGNER P. DEMPSEY AND VERIFIED BY J. BATTLEY J. PIRRONE J. TAYLOR	FIELD REPRESENTATIVE OFFICE COMPILER DIGITIZER DATA PROCESSER

National Archives Data
TP-00454

1 Discrepancy print (paper copy)
1 Field edit sheet (stable base copy)
1 NOAA Form 76-36 C (History of Field Operations)
5 NOAA Forms 76-40 (Working Copies Nonfloating Aid or Landmarks for Charts)
4 Pages of sextant cuts

Photography:

72K6379
73L(C)2795R, 2796R