### 

17 64 11 1 1 6 85 A					
Form 504					
U. S. COAST AND GEODETIC SURVEY					
DEPARTMENT OF COMMERCE					
DESCRIPTIVE REPORT					
·					
Type of Survey Planimetric					
Field No. Office No. T-9185 Project Ph-36(48)A					
LOCALITY					
State Texas					
General locality Corpus Christi Bay					
Locality Aransas Pass					
19 <b>6</b> L					
CHIEF OF PARTY C.W.Clark, Chief of Field Party					
Hubert A. Paton, Baltimore Photo. Office					
LIBRARY & ARCHIVES					
DATE					

### DATA RECORD

9185

Project No. (II): PH-36(48)A

Quadrangle Name (IV):

Arancas Pass

Field Office (II):

CORPUS CHRISTI, TEXAS

Chief of Party: C.W.Clark

Photogrammetric Office (III): BALTIMORE, MD.

Officer-in-Charge: Hubert A. Paton

Instructions dated (II) (III):
14 February 1949, Supplement No. 2(Field)
26 July 1949 and 28 July 1949 8 June 1949

Copy filed in Division of Photogrammetry (IV) Office Files

Method of Compilation (III):

GRAPHIC

Manuscript Scale (III): 1:20,000

Stereoscopic Plotting Instrument Scale (III):

Scale Factor (III): 1.000

Date received in Washington Office (IV): 3-1-50 Date reported to Nautical Chart Branch (IV): 3-3-50

Applied to Chart No.

892 Date: Feb 1952

Date registered (IV):

8-18-23

be published Publication Scale (IV): Not +>

Publication date (IV):

Geographic Datum (III): N. A. 1927

Vertical Datum (III):

Mean sea level except as follows:

Elevations shown as (25) refer to mean high water Elevations shown as (5) refer to sounding datum i.e., mean low water or mean lower low water

Reference Station (III): RAD, 1934

Lat.: 27°49' 23.252" (715.7m)

Long.: 97°03' 47.322" (1295.lm)

Plane Coordinates (IV):

State:

Zone:

Y=


X =

Roman numerals indicate whether the Item is to be entered by (II) Field Party, (III) Photogrammetric Office, or (IV) Washington Office.

When entering names of personnel on this record give the surname and initials, not initials only.

Form T- Page 1

M-2618-12(4)



Areas contoured by various personnel (Show name within area)
(II) (III)

PLANIMETRIC

### DATA RECORD

Field Inspection by (II): L.F.Beugnet Date: May 1949

Planetable contouring by (II): None Date:

Completion Surveys by (II): W.H. Shearouse Date: Sept 24, 1951

Mean High Water Location (III) (State date and method of location): 12-8-48

Identified on field photographs

W.E.W. 6-24-49
Projection and Grids ruled by (IV):

Projection and Grids checked by (IV): ,H.D.W. Date: 6-29-49

Control plotted by (III): F.J. Tarcza Date: 8-4-49

Control checked by (III): M.F.Kirk Date: 8-24-49

Radial Plot or Stereoscopic Date:

Control extension by (III): F.J. Tarcza 23 September 1949

Planimetry Date:
Stereoscopic Instrument compilation (iii):

Contours Date:

Manuscript delineated by (III): L.A.Senasack Date: 27 January 1950

Photogrammetric Office Review by (III): R.Glaser Date: 15 Feb. 1950

Elevations on Manuscript None Date: checked by (II) (III):

Form T-Page 3

M-2618-12(4)

U.S.C.& G.S. single lens, type 0, focal length, 6 inches Camera (kind or source) (III): U.S.C.& G.S. single lens, type C, focal length, 6 inches

		PHOTOGRAPHS (II	1)	
Number	Date	Time	Scale	Stage of Tide
48-0-1077 to 48-0-107	8 incl. 12-8-48	1002	1:20,000	Not computed
48-0-1095 to 48-0-109	7 incl. 12-8-48	1020	1:20,000	(Tide negligible)
48-0-1614 to 48-0-162	2 incl. 12-9-48	1131	1:20,000	n ñ
48-0-1650 to 48-0-165	6 incl. 12-9-48	1145	1:20,000	11 19
48-0-1809 to 1813 inc	1 12-9-48	1325	1:20,000	II II
48-0-1823 to 48-0-183	3 incl. 12-9-48	1340	1:20,000	tr tr
47-C-4080 to 47-C-408	2 incl. 1947		1:10,000	n n
47-C-4091 and 47-C-40	92 1947		1:10,000	11 11

Tide (III)

iue (III)

Reference Station: Galveston, Texas

Subordinate Station: Subordinate Station:

Washington Office Review by (IV): C. Theurer

Final Drafting by (IV):

El 2 funtion

Drafting verified for reproduction by (IV): Washing

Proof Edit by (IV):

Land Area (Sq. Statute Miles) (III): #2

Shoreline (More than 200 meters to opposite shore) (III):

Shoreline (Less than 200 meters to opposite shore) (III):

Control Leveling - Miles (II): 0

Number of Triangulation Stations searched for (II): 31

Number of BMs searched for (II):

Number of Recoverable Photo Stations established (III): 16

Number of Temporary Photo Hydro Stations established (III):

Diurnal

Ratio of Ranges	Mean Range	Range
1.0	1.0	1.4

Date: Oct 20, 1952

Data: 4-5-53

Date: 6-5-53

Date: 7-3-53


44 statute miles

12 statute miles

Recovered: 17
Recovered: 3

Identified: 16
Identified: 3

Remarks:



Froject Ph-36(48) conclute of filty-two quadrangles is 1:20,000, cash 7.5 blautes in Latitude and longitude, covering the bull deast of House and the Intraposatel Haterway from Arabas Bay to Brownsville and the Mexican Barder. Adjoining the project to the north is a perios of shoreline surveys in Pert IV of Project Ph-14(16).

parametica constant, M-36(NC) in its broader caposts will be included in a project completion report to be compiled at the consulation of the review of all surveys in this project.

weathy-fla of the quetrangles in this project are topographic surveys and are to be published at 1:24,000 sails by the Geological Survey. The other twenty-six quadrangles are planimetric surveys. Of these, ninescent are to be used as have by the Geological Survey for the compilation of 7.5 minute topographis quadrangles and will not be published as planimetric supps. The resalating severa, T-9175, T-9176, T-9177, T-9181, T-9109, T-9204, and T-9206, will be published as planimetric maps.

Floth-backed lithegraphic prints of the crigical new membership of constitution uselo and the descriptive reports for the maps in tale project will be filed in the Lurence Archives. Gloth-backed cupies of the published tracked questional outlished tracked question the filter.

All special reports except the Geog. Names Report will be filed in the Project Completion Report.

### 2. AREAL FIELD INSPECTION.

This quadrangle is located along the southeastern coast of Texas and just south of the town of Aransas Pass. The land area is composed of parts of Harbor Island, Mustang Island and St. Joseph Island and is in the counties of Aransas and Nueces.

The small town of Port Aransas is principally a resort town and the major occupation is the renting of boats and guides for offshore or inshore fishing trips. Large quantities of oil are also loaded into tankers at the port. Port Aransas is connected to the mainland to the north by a privately owned, toll causeway.

Aransas Pass affords an outlet to the Gulf of Mexico for sea going vessels.

The area along the gulf shore is covered by high sand dunes which give way to lower dunes covered by grass and low brush to the westward. The area is not suitable for agricultural products but a few cattle are grazed on the islands.

Field inspection is believed to be adequate and complete.

Along the west shore of Mustang Island, the sand dunes covered with vegetation give way to low sand and mud flats. These flats flood intermittently on spring and storm tides and at such times as high, sustained westerly winds push the water toward that shore.

One item was left for the field editor. Dredging operations in Aransas Channel were in operation and the spoil was being dumped on both sides of the causeway. The spoil will affect the mean high water line in places and this should be indicated by the field editor. The spoil has been indicated on the photographs so far as had been dredged at the time of the field inspection of this quadrangle.

### HORIZONTAL CONTROL

All U. S. Coast and Geodetic Survey Control was searched for or recovered. The following stations are classified lost.

POGY - 1934
HERD - 1933
ARANSAS PASS AND WAREHOUSE TERMINAL TANK - 1933
CLIME POINT BEACON - 1934
ST JOSEPH ISLAND BEACON - 1934
PORT ARANSAS GOVERNMENT DOCK BEACON - 1934
ARANSAS PASS, SPUR DYKE BEACON NO. 4 - 1934
ARANSAS PASS REAR RANGE BEACON - 1934
CORPUS CHRISTI CHANNEL EXTREME REAR RANGE BEACON - 1934
TURTLE COVE CHANNEL, REAR RANGE - 1934

One U.S.E. station of third-order accuracy was identified for Horizontal Control.

### 4. VERTICAL CONTROL

Port Aransas Tidal Bench Marks Nos. 5, 6, and 7 were recovered and identified on the photos. Four other Bench Marks were searched for but not recovered. The order of accuracy of the Bench Marks were unknown by this party.

No additional vertical control was established by this party  $\bullet$ 

### 5. CONTOURS AND DRAINAGE

As this is a planimetric map no contouring was done.

The only drainage in the area is run off directly into Aransas and Corpus Christi Bays and the Gulf of Mexico. No drainage was indicated on the field photographs.

### 6. WOODLAND COVER

Scattered masquite and scrub oak are found in the area. Where an appreciable area was covered, classification was in accordance with Photogrammetry Instructions No. 21, dated 18 August 1948.

### 7. SHORELINE AND ALONGSHORE FEATURES

Sce Raim Report - T9180
Shoreline inspection was done in accordance with "Field
Memorandum No. 1 - Mean High Water Line in Swamp and Other
Marsh Areas," dated 20 June 1938 and "Supplemental Instructions Shoreline Inspection," dated 18 March 1944.

Attention is called to the area around Harbor Island. Here the approximate limits of the marsh and grass in water have been indicated on the photographs.

There is no evident low water line within the limits of this quadrangle. In general, the mean low water line is parallel to and very close to the mean high water line.

All dock, wharves and piers are adequately covered by field inspection notes on the photographs.

All shore ends of submarine cable crossings have been located and identified on the photographs.

### 8. OFFSHORE STRUCTURES

Two submerged wrecks are recommended to be investigated by a hydrographic party. One is in Aransas Pass near the south jetty, Latitude 27° 50¹, Longitude 97° 02¹ 30″. The other in the Channel to the east of Aransas Pass Lighthouse Latitude 27° 51¹ 40″.

WRECK REMOVES

11/19/51

The only other offshore features are the two jetties at the entrance of Aransas Pass into the Gulf of Mexico. These jetties are constructed of concrete with rock piled on both sides and are readily visible on the photographs.

### 9. LANDMARKS AND AIDS

One landmark was selected for nautical charts. See form 567 submitted for this quadrangle.

See "Special Report, Location of Fixed Aids to Navigation, Project Ph-36(48) Latitude 28° 00' to Baffin Bay."

### 10. BOUNDARIES, MONUMENTS AND LINES

See "Special Report, Boundaries, Baffin Bay to Latitude 28° 00', Project Ph-36(48)".

### 11. OTHER CONTROL

The following Recoverable Topographic Stations were established for location by the radial plot.

ECHO

CON

USE STATION (UNSTAMPED)

HILL

SE CORNER UNIVERSITY OF TEXAS TRACT

NE CORNER UNIVERSITY OF TEXAS TRACT

MW CORNER TRACT "B"

SW CORNER USED RESERVATION

SE CORNER USED RESERVATION

NE CORNER TRACT "B"

SE CORNER LIGHTHOUSE RESERVATION

Form 524 is submitted for all stations

### 12. OTHER INTERIOR FEATURES

All roads were classified in accordance with Photogrammetry Instructions No. 10, dated 14 April 1947 as amended 24 October 1947.

Buildings and structures were classified in accordance with Photogrammetry Instructions No. 29 dated 1 October 1948.

There are no bridges over navigable water in the area.

One small airport is located southwest of the town of Port Aransas. The runways are surfaced with shell and is suitable for small light craft only. The runways were located on the photographs by planetable methods.

### 13. GEOGRAPHIC MAMES

The field investigation of Geographic names is in progress. All names will be found in a special report, the title and area covered by the report are not known at this time.

### 14. SPECIAL REPORTS AND SUPPLEMENTAL DATA

The following are Special Reports and other Supplemental data affecting this map.

"Special Report, Boundaries, Baffin Bay to Latitude 28° 00', Project Ph-36(48)."

A Special Report on Geographic Names.

"Special Report, Location of Aids to Navigation Project Ph-36(48), Latitude 28° 00' to Baffin Bay.

A Special Report on Coast Pilot Information.

Letter of Transmittal, Ph-36, Field-10.

Submitted: 17 June 1949

I. A. FITZGERALD Cartographer

Approved: 21 June 1949

Charles W. Clark
Lt. Comdr. USC&GS
Chief of Party

R 1.000	FACTOR DISTANCE FROM GRID OR PROJECTION LINE IN METERS FORWARD (BACK)												•								Pa	ge	12		26, 1949 M.238B-12
SCALE FACTOR 1.000	N.A. 1927 - DATUM DISTANCE FROM GRID OR PROJECTION LINE IN METERS FORWARD (BACK)		161.9 (162.9)			378.3 (1263.6)	200.7 (1323.3)	781.6 (742.5)	1617.4 (229.5)	1522.6 (119.1)	1398.8 (125.2)	448.2 (1075.8)	273.9 (1250.1)	694.1 (830.0)	1523.6 ( 0.4)	627.7 (896.3)	129.3 (1394.7)	240.5 (1283.5)	1372.3 (474.5)	1496.8 (144.7)	1535.9 (310.9)	602.3 (1039.2)	1315.7 (531.1)	1573.8 (67.7)	rg DATE July 26,
SCALE OF MAP 1:20,000	DISTANCE FROM GRID IN FEET.  DR PROJECTION LINE IN METERS FORWARD (BACK)						658.52 (4341.48)	2,564.14 (2435.86)	•		4,589.27 (410.73)	1,470.34 (3,529.66)		2,277.08 (2,722.92)	4,998.74 (1.26)	2,059.27 (2,940.73).		789.05 (4,210.95)							M.L.Rosenberg
PROJECT NO. Ph-36(48)A	LATITUDE OR y-COORDINATE LONGITUDE OR x-COORDINATE	8 5	27 50 05.259	90	50	97 06 13.824	790,658.52	2,467,564,14	27 50 52.544	97 03 55.649	794,589.27	2,461,470.34	790,898.51	2,462,277.08	789,998.74	2,452,059.27	790,424.22	2,445,789.05	27 51	97 02	27 51 49.898	97 03 22.015	27 51 42.745	97 02 57.527	nare July 21, 1949
PROJE	SOURCE OF DATUM	Field N.A.		=		=	USE (Special TEXAS		1 N	•	USE TEXAS Special SOUTH	teport on GRID	• Auron• ddne	# #	<b>E</b>		=	-	<u></u>		 	P.152 #	G-2874	22	
MAP T. 9185	STATION	CORPUS CHRISTI	HRISTI	CHANNEL LIGHT 7,	CORPUS CHRISTI	۱ ٠			HARBOR ISLAND RANGE REAR LICHT.		FENCE(USE).1948		4062 (USE) 1948		COW (USE) 1948	,	1EO (11SE) 1948		SUP. PT: RM No.1	POGY 1934	PASS LIGHT		POGY, 1934		1 FT. = 3048006 METER COMPUTED BY. F. J. Tarcza

•										
STATION	SOURCE OF INFORMATION (INDEX)	DATUM	LATITU	DE OR #-	LATITUDE OR #-COORDINATE	DISTANCE FROM GRID IN FEET.  OR PROJECTION LINE IN METERS	DATUM		N.A. 1927 - DATUM DISTANCE FROM GRID OR PROJECTION LINE	FACTOR DISTANCE FROM GRID OR PROJECTION LINE
PORT ARANSAS COAST	G-2874	A	Ę	1	ראז אר			509.1	(1337.7)	TORWARD (BACK)
GUARD WEATHER	P.81	1927	60	38	30 871.			7 000	(2,0,0)	
PORT ARANSAS COAST	G-2874		27	3   5	15.537			077.0	(19/6/)	
GUARD CUPOLA, 1934	P.81	=	797	03	32,380			4/00	(1,000,0)	
	0-287L		:   ;	;				886.0	886.0 (755.8)	
RAD, 1934	109 0	=	27	67	23.252			715.7	(1131.1)	
	7.0	:	97	03	47.322			1295,1	(347.0)	
SUB.PT. RAD, 1934		•	27	64				723.1	(1123.7)	
			26	03	:			1261.1	(381.0)	
KNOLL, 1934	G-2874		23	14	31.964			983.9	(863.0)	
	P. 55	<b>#</b>	26	05	13,902			380.6	(1262.0)	
SUB.PT. KNOLL,		1	22	47				1142.3	(4.6)	144
4661		L·-	26	05				402.2	(1240.4)	
HARBOR. ISLAND, RANGE			27	50	43.718			1345.7	(501.2)	
FRONT LIGHT, 1949	P.3	=	67	ප	39.228			1073.4	(7995)	
CHANNEL CHRISTI.	0-8133	. 2	27	50	20,088			618.3	(1228.5)	
1949		:	97	70	52,896			1447.4	(194.4)	
		,—- <b>-</b>								
			ļ							
										Page
										e 13
										The state of the s

### COMPILATION REPORT

### T - 9185

### PHOTOGRAMMETRIC PLOT REPORT

Refer to radial plot report for this area which is bound with the descriptive report for T-9175.

### 31. <u>DELINEATION</u>

This survey was delineated by graphic methods only.

Cattle trails and ponds are delineated as recommended in a letter from Lt. Comdr. Charles W. Clark to the Director, dated 14 June 1949.

All boundaries were delineated using data obtained from "Special Report on Boundaries, Baffin Bay to latitude 28°, dated May 1949 and supplemented by boundary maps furnished by the field party. At least one boundary corner was identified on the field photographs for all boundaries except the U.S. Military Reservation just north of Aransas Pass on St. Joseph Island. All bearings given for boundaries were accepted as true bearings.

A discrepancy overlay is being submitted with the manuscript.

### 32. CONTROL

The identification, density and placement of the horizontal control was adequate. See radial plot report concerning identification of GUN (USE) 1948.

### 33. SUPPLEMENTAL DATA

Geographic Names Standards No. 1, 2, and 4, dated 4 November 1949, were furnished by the Washington Office.

Special Report Boundaries-Aransas Bay to Baffin Bay, Project Ph-36 (48).

Boundary Sheet 22, Map of Yardcraft Facility Port Aransas, Texas.

Boundary Sheet 20, Aransas Pass Lighthouse Reservation extended to Harbor Line.

Boundary Sheet 30, Port Aransas, Texas, Lands to be exchanged.

Boundary Sheet 1, Aransas County, General Land Office, Austin, Texas.

Boundary Sheet 3, Nueces County Highway Map.

Special Report, Location of Aids to Navigation, Project Ph-36(48) Latitude 28° 00' to Baffin Bay.

### 33. SUPPLEMENTAL DATA (continued)

Special Report on Supplemental Control, Project Ph-36(48) Latitude 28°00' to Baffin Bay.

### 34. CONTOURS AND DRAINAGE

Refer to item 5 of this report.

### 35. SHORELINE AND ALONGSHORE DETAILS

Refer to item 7 of this report.

Shoreline inspection was adequate

Shoal lines were delineated from office interpretation of the photographs.

### 36. OFFSHORE DETAILS

Refer to item 8 of this report.

### 37. LANDMARKS AND AIDS

Form 567 for 24 non-floating aids to be charted are being submitted with this report. Also being submitted herewith are forms 567 for one landmark to be charted and one landmark to be deleted.

The Corpus Christi Channel Cut A East Range Front and Rear Lights were radially plotted from identification on photograph 47-C-4092 (Ph-14(46). Some difficulty was encountered in locating the position of the rear range light on the PH-36(48) photographs. Additional data on these lights accompany this report in letter No. 7312-rb from the Chief, Division of Photogrammetry, dated 9 December 1949, and on Forms 524 submitted by the field party for Ph-14(46). It is noted that the adjusted geographic positions of these lights as listed in the above mentioned letter are considered to be of only fourth order accuracy, whereas, the same positions subsequently received on geographic position forms are listed as being of third order accuracy.

### 38. CONTROL FOR FUTURE SURVEYS

Forms 524 for a total of nineteen recoverable topographic stations are being submitted with this report. Eleven of these stations, submitted by the 1949 field party under Lt. Comdr. C. W. Clark, are listed in item 11 of this report. An additional form 524 for ARANSAS PASS RADIO BEACON was submitted by the same party but was not listed. The forms for the remaining seven stations were submitted by the field party for project PH-14(46) under Lt. Comdr. Ross A. Gilmore; they are as follows:

CORPUS CHRISTI CHANNEL CUT A EAST RANGE FRONT LIGHT CORPUS CHRISTI CHANNEL CUT A EAST RANGE REAR LIGHT ARANSAS PASS DREDGING SOUTH SIDE RANGE FRONT DAYBEACON Ħ 11 11 11 REAR 11 п п NORTH Ħ 11 rt Ħ 11 tř 11 FRONT HARBOR ISLAND REAR RANGE BEACON, 1934

A list of the mineteen recoverable topographic stations is included in item 49 of this report.

### 39. JUNCTIONS

Junctions with Surveys No. T-9179 to the north and T-9184 to the west have been made and are in agreement. To the east and south are water areas.

### 40. HORIZONTAL AND VERTICAL ACCURACY

No comment.

### 41. LANDING FIELDS AND AERONAUTICAL AIDS

Refer to item 12 paragraph 4 of this report.

No aeronautical aids have been reported for the area of this survey.

### 42 to 45.

Inapplicable.

### 46. COMPARISON WITH EXISTING MAPS

This manuscript was compared with the U. S. Geological Surveys Aransas Pass, Texas, quadrangle, scale 1:62,500 edition of 1925, reprinted 1945.

### 47. COMPARISON WITH NAUTICAL CHARTS

Survey No. T-9185 has been compared with U.S.C.& G.S. Chart No. 523, scale 1:40,000, published 10 October 1949 corrected to 19 December 1949, No. 1285, scale 1:80,000, published 28 February 1949 corrected to 23 January 1949 and No. 1286, scale 1:80,000, published 1 August 1949 corrected to 12 December 1949.

### 47. COMPARISON WITH NAUTICAL CHARTS (continued)

Items to be applied to nautical charts immediately None.

Items to be carried forward
None

Respectfully submitted 27 January 1950

Leroy A Senasack

Cartographic Survey Aid

Approved and forwarded 28 February 1950

Hubert A. Paton Comdr., US C&GS Officer in Charge Aransas Channel
Aransas County

\* Aransas Pass Lighthouse Aransas Pass

Commissioner Precinct 1
Commissioner Precinct 4
Corpus Christi Bay
Corpus Christi Channel

East Flats

- . Gulf of Mexico
- Harbor Island
  Holiday Beach
- Lydia Ann Channel
- Morris and Cummings Cut
  Mustang Island
- North Jetty Nueces County
- Port Aransas Causeway
- South Jetty
  South Pier
  St. Joseph Island
  - U. S. Military Reservation
  - \* Triangulation station (geographic name does not appear on manuscript)

Names underlined in red are approved.

4-2-51

1.Heck

· Cline Point (recently reapplied to nautical Humble Basin

### 49. NOTES TO THE HYDROGRAPHER

The following is a tabulation of recoverable topographic stations shown on the manuscript:

ARANSAS PASS DREDGING NORTH SIDE RANGE FRONT DAYBEACON ARANSAS PASS DREDGING SOUTH SIDE RANGE REAR DAYBEACON ARANSAS PASS DREDGING SOUTH SIDE RANGE FRONT DAYBEACON ARANSAS PASS RADIO BEACON

CORPUS CHRISTI CHANNEL CUT A EAST RANGE FRONT LIGHT CORPUS CHRISTI CHANNEL CUT A EAST RANGE REAR LIGHT COWI (USE) (Same as A COW (USE), 1948

ECHO

HARBOR ISLAND REAR RANGE BN., 1948 (Same as A HARBOR ISLAND RANGE REAR LT., 1949)

S.E. CORNER LIGHTHOUSE RESERVATION

NE CORNER TRACT "B"

NW CORNER TRACT "B"

NE CORNER UNIVERSITY OF TEXAS TRACT

SE CORNER UNIVERSITY OF TEXAS TRACT

SE CORNER U.S.E.D. RESERVATION

SW CORNER U.S.E.D. RESERVATION

U.S.E. STATION (unstamped) (Same as A LEO (U.S.E.), 1948)

The following is an excerpt from item 8 of the field inspection report:
"Two submerged wrecks are recommended to be investigated by a
hydrographic party. One is in Aransas Pass near the south jetty,
latitude 27° 50' longitude 97° 02' 30". The other is in the
channel to the east of Aransas Pass Lighthouse, latitude 27°51'40".

M-2623-12

50.

43. Remarks:

### PHOTOGRAMMETRIC OFFICE REVIEW

T. 9185

1. Projection and grids 2. Title 2. 3. Manuscript numbers 4. Manuscript size
CONTROL STATIONS
5. Horizontal control stations of third-order or higher accuracy 6. Recoverable horizontal stations of less
than third-order accuracy (topographic stations) h. 7 Photo hydro stations 8. Bench marks 42
than third-order accuracy (topographic stations)
ALONGSHORE AREAS
(Nautical Chart Data)
12. Shoreline 13. Low water line 14. Rocks, shoals, etc. 15. Bridges 16. Alds to navigation 17. Landmarks 18. Other alongshore physical features 19. Other along -
to navigation17_ Landmarks18. Other alongshore physical features19. Other along -
shore cultural features
PHYSICAL FEATURES  20. Water features 21. Natural ground cover 22. Planetable contours 23. Stereoscopic linstrument contours 24. Contours in general 25. Spot elevations 26. Other physical
20. Water features 21. Natural ground cover 22. Planetable contours 23. Stereoscopic
Instrument contours 24. Contours in general 25. Spot elevations 26. Other physical
features
CULTURAL FEATURES  27. Roads 28. Buildings 29. Railroads 30. Other cultural features 25.
BOUNDARIES
31. Boundary lines
A MISCELLANEOUS
MISCELLANEOUS  33. Geographic names 34. Junctions 35. Legibility of the manuscript 36. Discrepancy
overlay 37. Descriptive Report 38. Field inspection photographs 39. Forms
40. Paymond Slase  Reviewer Supervisor, Review Section or Unit
, Action of Office
41. Remarks (see attached sheet)
FIELD COMPLETION ADDITIONS AND CORRECTIONS TO THE MANUSCRIPT
42. Additions and corrections furnished by the field completion survey have been applied to the manuscript. The manuscript is now complete except as noted under item 43.
The state of the s
Compiler Supervisor

### DEPARTMENT OF COMMERCE U. S. COAST AND GEODETIC SURVEY

Y POST-OFFICE ADDRESS:

Washington

Re: 7312-rb

**TELEGRAPH ADDRESS:** 

9 December 1949

**EXPRESS ADDRESS:** 

To:

Comdr. Hubert A. Paton U. S. Coast and Geodetic SURvey 518 East 32nd Street Baltimore 18, Maryland.

Subject:

Computed positions of lights, Corpus Christi Channel Cut "A" - Project Ph-36

Mr. Steinberg recently requested information of this office on whether or not Corpus Christi Channel Cut "A" Front and Rear Bange Lights were being computed in this office.

The Division of Geodesy encountered considerable difficulty in computing the positions for both of these lights, and the adjusted positions, as follows, are considered to be of only fourth order accuracy:

Corpus Christi: Channel Cut "A" East Range Front 27 - 50 - 40.771 (1255.0), 97 - 03 - 16.914 (465.4), Rear 27 - 50 - 44.791 (1377), 97 - 02 - 54.970 (1557.1),

The adjusted values for the remainder of Comdr. Clark's work in this area will be available in about two weeks, at which time copies will be furnished to you.

Because of the low order of accuracy obtained in locating Corpus Christi Channel Cut "A" East Range Lights, Front and Rear by triangulation methods, it is suggested that you locate these lights by radial plot methods, if practicable, and use the computed positions as a check.

O.S.Reading Chief, Div. of Photogrammetry

B	3	3	ŀ	
ì	÷	ı		
i	ú	á	t	
	٤	ı	-	i
	í	ı	1	•
	•		o.	

### DEPARTMENT OF COMMERCE

U. S. COAST AND GEODETIC SURVEY

## MONTED METING ALDS OR LANDMARKS FOR CHARTS

TO BE CHARTED STRIKE OUT ONE TO BE DELETED

The positions given have been checked after listing by

Corpus Christi, Texas

1 June

I recommend that the following objects which have (have mack been inspected from seaward to determine their value as landmarks be charted on (deleted refrance) the charts indicated.

523, 128 CHARTS GRARLES W. CLARK Chief of Party. This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating OFFSHORE CHART INSHORE CHART × HARBOR CHART LOCATION DATE PO 1934 METHOD OF LOCATION AND SURVEY No. T-9185 TH N.A. 1927 DATUM 15/ D. P. METERS 886.0 LONGITUDE 97 03 POSITION 0 110 4.78.2 D.M. METERS LATITUDE 20 0 27 SIGNAL Port Aransas Coast Guard DESCRIPTION Cupola, 1931) Coast Guard Texas CHARTING CUP STATE

aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by indicated to a constant of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by assure the charts of the area and not by a second the charts of the area and not by a second the charts of the U. S. GOVERNMENT PRINTING OFFICE: 1949 0 - 853418

Form 567 April 1945

DEPARTMENT OF COMMERCE

U. S. COAST AP SEODETIC SURVEY

## MONFEDATING AIDS OR LANDMARKS FOR CHARTS

TOX BEX CHARRED STRIKE OUT ONE

Corpus Christi, Texas

1 June

19 49

I recommend that the following objects which have (mayorate) been inspected from seaward to determine their value as landmarks be TO BE DELETED

xhartedox (deleted from) the charts indicated.

The positions given have been checked after listing by

Chief of Party. CLARK CHARLES W.

CHARTS 523 OFFSHORE CHART INSHORE CHART × HARBOR CHART LOCATION DATE 1931 METHOD OF LOCATION AND SURVEY NO. Tri. DATUM 1987 1254.3 D. P. METERS (44) LONGITUDE 25 69 POSITION - 0 6 一十十十 D. M. METERS 1649.9 LATITUDE 2 0 23 SIGNAL This tank is no longer in existence (Aransas Pass, Warehouse and Terminal Co. Tank, 1931) DESCRIPTION On Harbor Island Texas CHARTING STATE TANK

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by U. S. GOVERNMENT PRINTING OFFICE: 1949 O - 853418 ... shorte Information under each column heading should be given. . . . . 1 2 13 ...

Form 567 April 1945

### DEPARTMENT OF COMMERCE

GEODETIC SURVEY U. S. COAST A

## NONFLOATING AIDS OR PROPORTING FOR CHARTS

STRIKE OUT ONE TO BE CHARTED DOXBEXDEDEDEDED

Baltimore, Maryland

26 January

19 50.

I recommend that the following objects which have (navexnand been inspected from seaward to determine their value as landmarks be charted on (daletedx from the charts indicated.

R. Glaser The positions given have been checked after listing by

Chief of Party. Hubert A. Paton

Aransas Pass   Aransas   Aransas Pass   Aransas   Aransas   Aransas Pass   Aransas   Aransas		Texas				POSITION	NOI			METHOD			CHAR
### Aransas Pass Lighthouse, 1931) 3611 27 51 1536 97 03 602 4	DIAIE		List No.		LATITUDE		LONGIT	JDE	200	LOCATION	OF	OBE CH	CHARTA AFFECTE
Aransas Pass         Aransas Pass         3611         27         51         1536         97         03         602           Aransas Pass         Lighthouse, 1931         3611         27         51         1491         97         03         634           Aransas Pass         Harbor Island Range Front         4485         27         50         1346         97         03         1073           Aransas Pass         Aransas Pass         Aransas Pass         4491         27         50         1617         97         03         1673           Aransas Pass         Aransas Pass <t< th=""><th>CHARTING</th><th>DESCRIPTION</th><th>SERVICE NO.</th><th>0</th><th>D.M.METE</th><th></th><th></th><th></th><th>Σ</th><th>T-9185</th><th>LOCATION</th><th>用工工人</th><th>183</th></t<>	CHARTING	DESCRIPTION	SERVICE NO.	0	D.M.METE				Σ	T-9185	LOCATION	用工工人	183
t Harbor Island Range Front 4485 27 50 1346 97 03 1073  t Harbor Island Range Front 4486 27 50 1346 97 03 1073  t Aransas Pass 11  t Cline Point Happ 27 50 1617 97 03 1523  t Cline Point Happ 27 50 913 97 03 33  t Corpus Christi Channel Cut A 4500 27 50 1253 97 03 1062  t Corpus Christi Channel 1 4501 27 50 1378 97 02 1506  t Corpus Christi Channel 2 4504 27 50 1409 97 04 1447  t Corpus Christi Channel 2 4504 27 50 1409 97 04 1447  t Corpus Christi Channel 2 4504 27 50 1378 97 04 1447  t Corpus Christi Channel 2 4504 27 50 180 97 04 1447  t ★ Corpus Christi Channel 2 4504 27 50 180 97 04 1447  t ★ Corpus Christi Channel 2 4504 27 50 180 97 04 1447  t ★ Corpus Christi Channel 2 4504 27 50 162 97 06 343	Light	Aransas Pass Lichthonse, 1931)	3611	27			63		N.A.	Triang.	1931	×	x 523-100
Harbor Island Range Front 4485 27 50 1346 97 03 1073  Harbor Island Range Front 4486 27 50 1617 97 03 1523  Aransas Pass 11  Aransas Pass 11  Cline Point 4493 27 50 913 97 03 591  Corpus Christi Channel Cut A 4500 27 50 1253 97 03 944  Corpus Christi Channel 1 4503 27 50 1378 97 02 1506  Corpus Christi Channel 2 4504 27 50 1253 97 04 1447  Corpus Christi Channel 2 4504 27 50 618 97 04 1447  Corpus Christi Channel 2 4504 27 50 618 97 04 1447  Corpus Christi Channel 2 4505 27 50 618 97 04 1447	Radio	Aransas Pass	3611	27			03	634	m)	Photo.	19/,9	×	×
Harbor Island Range Bear 4486 27 50 1617 97 03 1523  Aransas Pass 11  Cline Point  Cline Point  Liustang Island Fog Signal  Lustang Island Fog Signal  Corpus Christi Channel Cut A  Corpus Christi Channel Cut A  Corpus Christi Channel Lut A  Ly500 27 50 912 97 03 944  Corpus Christi Channel Cut A  Ly501 27 50 1253 97 02 1506  Corpus Christi Channel Lut A  Ly502 27 50 1278 97 02 1447  Corpus Christi Channel Lut A  Ly503 27 50 1378 97 04 1447  Corpus Christi Channel L  Ly504 27 50 1378 97 04 1447  Corpus Christi Channel L  Ly504 27 50 162 97 04 1447  Corpus Christi Channel 2  Ly504 27 50 162 97 04 1447	Light	Harbor Island Range Front	4485	27				1073	=	Triang.	1949	×	523
Aransas Pass II 4491 27 50 546 97 03 33  Cline Point  Port Aransas Chennel 2 4494 27 50 913 97 03 1062  Rustang Island Fog Signal 4495 27 50 912 97 03 1062  Gorpus Christi Channel Cut A 4500 27 50 1253 97 03 464  Corpus Christi Channel I 4501 27 50 1378 97 02 1506  Corpus Christi Channel I 4503 27 50 618 97 04 1447  Corpus Christi Channel 2 4504 27 50 780 97 04 1447  Corpus Christi Channel 2 4504 27 50 162 97 06 343	Light	Harbor Island Range Rear	44,86	27			63	1523	=			×	=
Cline Point Port Aransas Chennel 2 4494 27 50 913 97 03 1062  Nustang Island Fog Signal 4495 27 50 912 97 03 1062  Corpus Christi Channel Cut A 4500 27 50 1253 97 03 464  Corpus Christi Channel 1 4501 27 50 1378 97 04 1447  Corpus Christi Channel 1 4504 27 50 618 97 04 1447  Corpus Christi Channel 2 4504 27 50 780 97 04 1447  Corpus Christi Channel 2 4504 27 50 780 97 04 1447	Light	Aransas Pass 11	1644	27			63	33		Photo	=	×	2
Port Aransas Chennel 2   4494   27 50 943 97 03 1062     Mustang Island Fog Signal   4495   27 50 912 97 03 944     Corpus Christi Channel Cut A   4500   27 50 1253 97 03 464     East Range Front   4501   27 50 1378 97 02 1506     Corpus Christi Channel 1   4503   27 50 618 97 04 1447     Corpus Christi Channel 2   4504   27 50 780 97 04 1479     Corpus Christi Channel 2   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 343     Corpus Christi Channel 7   4505   27 50 162 97 06 97 04     Corpus Christi Channel 7   4505   27 50 162 97 06 97 04     Corpus Christi Channel 7   4505   27 50 162 97 06 97 04     Corpus Christi Channel 7   4505   27 50 162 97 06 97 04     Corpus Christi Channel 7   4505   27 50 162 97 06 97 04     Corpus Christi Channel 7   4505 97 06 97 07 07 07 07 07 07 07 07 07 07 07 07 07	Light	Cline Point	14493	27		-	8	591		=	-	×	=
Mustang Island Fog Signal         4495         27         50         912         97         03         944           Corpus Christi Channel Cut A East Range Front         Lorpus Christi Channel Cut A L500         27         50         1253         97         03         464           Corpus Christi Channel I         4501         27         50         1378         97         02         1506           *         Corpus Christi Channel I         4503         27         50         618         97         04         1447           *         Corpus Christi Channel 2         4504         27         50         780         97         04         1479           *         Corpus Christi Channel 7         4505         27         50         162         97         04         1479	Licht	Port Aransas Channel 2	4644	27			Activities of the	290	=	=	=	×	=
Corpus Christi Channel Cut A         4500         27         50         1253         97         03           Corpus Christi Channel Cut A         4501         27         50         1378         97         02         1           Corpus Christi Channel 1         4503         27         50         618         97         04         1           * Corpus Christi Channel 2         4504         27         50         780         97         04         1           Corpus Christi Channel 7         4505         27         50         162         97         06	9_0	West and Teland For Stone	74495	27			63	476	=	E No.	=	×	=
Gorpus Christi Channel Cut A       4501       27       50       1378       97       02       1         Corpus Christi Channel 2       4503       27       50       618       97       04       1         Corpus Christi Channel 2       4504       27       50       780       97       04       1         Corpus Christi Channel 7       4505       27       50       162       97       06       1	Light	42	4500	27			03	797	=	=	=	×	=
# Corpus Christi Channel 1 4503 27 50 618 97 04 1  # Corpus Christi Channel 2 4504 27 50 780 97 04 1  Corpus Christi Channel 7 4505 27 50 162 97 06	Light	Cut	4501	27			02	1506	=		E	×	=
# Corpus Christi Channel 2 4504 27 50 780 97 04 1 Corpus Christi Channel 7 4505 27 50 162 97 06	Light	Corpus Christ Channel 1	4503	27				7447	=	Triang	± 00	×	=
Corpus Christi Channel 7 4505 27 50 162 97 06		Corpus Christi Channel 2	4504	27			70	7479	=	-	=	×	=
	Licht	Corons Christi Channel 7	4,505	27			90 ,	343	=	=	=	×	***
8 4506 27 50 528 77 00		Corpus Christi Channel 8	4506	27	50, 3		90 46	378	= /	=	-	XX	=

aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given. This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating U. S. GOVERNMENT PRINTING OFFICE: 1949 0 - 853418

Form 567 April 1945

### DEPARTMENT OF COMMERCE

U. S. COAST ATT GEODETIC SURVEY

# NONFLOATING AIDS ORCIANDMARKS FOR CHARTS

TO BE CHARTED ST

STRIKE OUT ONE

Baltimore, Md.

26 January 1950

I recommend that the following objects which have (haraconook been inspected from seaward to determine their value as landmarks be charted on (delated x forms) the charts indicated.

The positions given have been checked after listing by R. Glaser

									nuperr	nupert A. Faton		Chief of Farty.
STATE	Texas				POSITION	N			METHOD		TRA	тяан
			LAT	LATITUDE	7	LONGITUDE			LOCATION	DATE		
CHARTING	DESCRIPTION	SIGNAL	- 0	D.M. METERS	0		D. P. METERS	DATUM	T-9185	Po	некво	OFFECTED OFFECTED
Daybeacon	Morris and Cummings Cut		27 52	266	97 (	07 92		N.A. 1927	Sextant	1949	×	523
	Aransas Causeway Channel & H		27 52	812	97 (	05 657				=	×	=
	Port Aransas Channel 1		27 50	968	97 (	03 982	-		=	=	×	
	Port Aransas Channel 3		27 50	840	97 (	03 980		#			×	-
	Port Aransas Channel 4		27 50	840	97 (	03 1050			•	•	×	
	Aransas Causeway Channel 2		27 50	1691	97 (	97 03 1108			E	1948	×	=
	Aransas Pass bredging South Side Range Front		27 50	1347	97 (	97 03 1199		=	Photo	1948		•
	Aransas Pass Dredging South Side Range Rear		27 50	1490	97 6	03 14.33				=	4 )	
	M	(2) 53	27 50	1397		03 1051			=		4 ×	
	Aransas rass breaging North Side Range Rear		27 50	1607	97 0	97 03 1381			=	•	×	
		Ch.	J Ku	e # a	1	215	(419)					
	7											
						The second named in column 2 is not a second		-				

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

### DEPARTMENT OF COMMERCE

Photogrammetric Review (petion

U. S. COAST AND GEODETIC SURVEY

# NONFLOATING AIDS OR/LANDMARKS/BOR/CHARTS//

Corpus Christi, Texas TO BE CHARTED STRIKE OUT ONE

I recommend that the following objects which have (nate) been inspected from seaward to determine their value as landmarks be The positions given have been checked after listing by 5 November

			Joseph	Joseph W. Vonasek	sek		1	0	1 Beneter	et.	
STATE								r. L.	L. Sernstein,		Chief of Party
					POSITION			METHOD		19/	
CHARTING	DESCRIPTION	SIGNAL	LATITUDE	UDE	LONG	LONGITUDE		LOCATION		SE CH	CHARTS
	Arangas Pass Dredaging North Side	NAME	-	D. M. METERS	- 0	D. P. METERS	DATUM	SURVEY No.	LOCATION	HARBO NSHOF	AFFECTE
Licens	Range Front (Skeleton steel tower with black slatted daymark, 50 feet high,		27 50	14,38	97 03	1103	N. A.	Flanstable T-9185	1951	. *	1285
* 6 7	Light atop)										
		77	ナ	etter	9	5/5					
			2								
E											THE REAL PROPERTY OF THE PERSON OF THE PERSO

### ADDENDUM TO

### COMPILATION REPORT

### T- 9185

### 31. DELINEATION

Comparison was made between the manuscript and nine lens photograph No. 25766, exposed in 1950. No revisions were made on the manuscript of that area covered by the above mentioned photograph since there were no apparent changes in the area not obscured by clouds.

Respectfully submitted 18 September 1950

Raymond Glaser

Surveying and Cartographic Aid

### Field Edit Report, T-9185

51. Methods. -- Field edit was accomplished by riding out all roads, by skiff and by riding the beach.

Planetable and tape methods were used for all additions. Sextant fixes were used to obtain the points on range and the position of Aransas Causeway Channel Daybeacon 4.

Field edit information is shown on the Field Edit Sheet and photograph 48-0-1077 and 1078. Violet ink was used for additions and corrections, and green for deletions.

- 52. Adequacy of compilation. The manuscript appears well-compiled and will be adequate after application of field edit information.
- 53. Map accuracy .-- No accuracy test was specified. From visual inspection, the accuracy of the map appears good.
  - 54. Recommendations .-- No recommendations are offered.
- 55. Examination of proof copy.--It is recommended that Mr. E. V. Tarrant, Mayor of Port Aransas, be sent the proof copy for examination. Mr. Tarrant is very familiar with the area and able to read a map with ease. He has agreed to make the examination. His address is P. O. Box 238, Port Aransas, Texas.

Respectfully submitted, 24 September 1951

William H. Shearouse, Cartographer

### Review Report T-9185 Planimetric Map October 20, 1952

### 62. Comparison with Registered Topographic Surveys .-

H-386 (Rec)	1:10,000	1854
T-720 (Rec)	1:50,000	1858
T-823	1:20,000	1860, 61, and 68
Misc. 8	1:20,000	1863
T-2354	1:10,000	1899
T-4872 (Graph Co	ntrol) 1:20,000	1934
T-6229 "	" 1:10,000	1934
T-5368 (Supp)	1:20,000	1934
т-5369 "	1:20,000	1934
T-6663 a & b (Gr	aph Control) 1:20	),000, 1938

This map supersedes these surveys for nautical charting purposes.

### 63. Comparison with Maps of other Agencies.

USGS, Aransas Pass Quadrangle, 1:62,500, 1925 Reprint 1945 The railroad shown on the USGS Quad to Port Aransas has been replaced by a highway.

Considerable industrial development has taken place at Port Aransas since the USGS Quad was published.

64. Comparison with Contemporary Hydrographic Surveys .- None

### 65. Comparison with Nautical Charts .-

Nautical Chart 523 1:40,000 1950

Three wrecks shown on the chart, one at Port Aransas, Not Definite one at Aransas Pass, and the other near Harbor Island, have been removed.

- 66. This map conforms with National Map Accuracy Standards. See Review Report, T-9176, for results of a horizontal accuracy test in this area.
- 67. Application to Nautical Charts.—The maps of this project were applied to a new series of Intracoastal Waterway Charts. This map has been applied to Chart Nos. 892 and 893. These maps have not been published at this date.

Reviewed by:

C. Theurer

### APPROVED:

Chief, Review Section Div. of Photogrammetry

Chief, Nautical Chert Branch Division of Charts

### NAUTICAL CHARTS BRANCH

### SURVEY NO. 79185

### Record of Application to Charts

DATE	CHART	CARTOGRAPHER	REMARKS
11/19/51	893	89. MoGam	Before After Verification and Review
Fab 1952	892	Norfolk	Before Mix Verification and Review Completely
10-8-53	1785	JACK ALLEY	Bases After Verification and Review Thru charts 8724 893
1/10/18	892	Jane Gem	- Beface After Verification and Review
1-5-54	1286	n. D. Huderson	Before After Verification and Review
	·		Before After Verification and Review
		·	Before After Verification and Review
	· ——— · ——		Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
	<del></del>		M-2168-1

M-2168-1

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.