

8089

Diag. Cht. No. 78-4

Form 504

U. S. COAST AND GEODETIC SURVEY

DEPARTMENT OF COMMERCE

DESCRIPTIVE REPORT

Type of Survey Air Photographic (Shoreline)

Field No. Office No. T-8089

LOCALITY

State Virginia

General locality James River

Locality Turkey Island - Hatcher Island

194 1-'43

CHIEF OF PARTY

H.O. Fortin, Chief of Field Party

F.L. Peacock, Balto. Photo. Office

LIBRARY & ARCHIVES

DATE July 17, 1950

B-1870-1 (1)

8089

DATA RECORD

Form T-1

T-8089 & T-8088

Quadrangle (II): Dutch Gap, Va. $7\frac{1}{2}$ minute
(U.S.G.S.)

Project No. (II): CS-283

Field Office: Air Photographic Party #2 Chief of Party: Henry O. Fortin
~~Fred. L. Peacock~~

Compilation Office:

Chief of Party: Fred. L. Peacock

Baltimore Photogrammetric Office

Div. of Photogrammetry
Office Files

Instructions dated (II III):

Copy filed in Descriptive

March 26, 1942-July 15, 1942-Sept. 30, 1942

~~Report No. T-~~

(VI)

Nov. 14, 1942 and Nov. 24, 1942

Completed survey received in office: 9-19-44

Reported to Nautical Chart Section:

Reviewed: 12-²¹~~27~~-48 Applied to chart No. 531Date: Partially 11-21-44
Completely 2-4-47

Redrafting Completed: 2-10-50

Registered: 6-20-50

Published:

Compilation Scale: 1:10,000

Published Scale:

Scale Factor (III): None

Geographic Datum (III): N.A. 1927

Datum Plane (III): MHW
~~Mean Sea Level~~

Reference Station (III): BOTTOM 1942, r. 1943

Lat.: 37-24' - 34.17" 0"
1053.4 (796.3) MetersLong.: 77°-18' - 20.80" 4"
511.5 (964.1) Meters ~~unadjusted~~
.6

State Plane Coordinates (VI): Virginia South Zone

X = 2,346,852.64 FT.

Y = 394,003.37 FT.

Military Grid Zone (VI)

PHOTOGRAPHS (III)

<u>Number</u>	<u>Date</u>	Eastern Standard <u>Time</u>	<u>Scale</u>	<u>Stage of Tide</u>
7622 to 7625 inc.	11-25-41	1:04 p.m.	1:10,000	1.0' above M.L.W.
7626 to 7627 inc.	11-25-41	1:12 p.m.	1:10,000	0.9' " "
7628 to 7631 inc.	11-25-41	1:20 p.m.	1:10,000	0.8' " "

Tide from (III), Predicted tables, Reference STA. Wash., D.C. corrections for
Deep Bottom, Va.

Mean Range: 3.2'

Spring Range: 3.7

Camera: (Kind or source) U.S.C.&G.S. 9 lens camera (focal length-8 $\frac{1}{4}$ ")
All negatives are on file in the Washington Office

Field Inspection by: Lt. Comdr. Henry O. Fortin

date: Winter 1942-1943

Field Edit by: None

date:

Date of Mean High Water Line Location (III): Date of photographs supplemented
by field inspection data obtained in 1942-1943. Season's Field inspection
reports previously submitted.

Projection and Grids ruled by (III) B.R.C.-J.T.B.
Washington Office

date: May 4, 1944

" " " checked by: B.R.C.

date: May 4, 1944

Control plotted by: James E. Sunderland, A.C. Rauck, Jr.

date: May 13, 1944 & Aug. 7/44
May 13, 1944 & Aug. 7/44

STATISTICS (III)

Land Area (Sq. Statute Miles): Shore line only

Shoreline (More than 200 meters to opposite shore): 21 statute miles

Shoreline (Less than 200 meters to opposite shore): 7 statute miles
Measured along approx. centerline of stream

Number of Recoverable Topographic Stations established: 11

Number of Temporary Hydrographic Stations located by radial plot: 57

Leveling (to control contours) - miles:

Roman numerals indicate whether the item is to be entered by,

(II) Field Party, (III) Compilation Party, or, (VI) the Washington Office.

When entering names of personnel on this record give the surname
and initials (not initials only).

Remarks;

Field Inspection

Field inspection data for the area of T-~~8089~~ are contained in the "Report on Field Inspection of Air Photographs, James River and Tributaries, Virginia" by Henry O. Fortin, dated April 20, 1943.

Filed in the Division of Photogrammetry, General Files.

26. CONTROL:

This Map Drawing includes that portion of the shoreline and adjacent planimetry of the James River and its tributaries falling within the area of Surveys Nos. T-8089 and T-8088.

The following horizontal control stations fall within the limits of the Map Drawing.

UNITED STATES COAST AND GEODETIC SURVEY SECOND ORDER TRIANGULATION STATIONS

- BRADY, 1942, 1943
- BREM, 1942
- BETHEL, 1942, 1943, r. 1943
- BOTTOM, 1942, r. 1943
- CURL, 1943, r. 1943
- ~~DUTCH, 1932~~ *Lost*
- HARR, 1942, 1943
- HAXALL, 1942, 1943
- MEADOW, 1932
- STONEMAN, 1943, r. 1943

UNITED STATES COAST AND GEODETIC SURVEY, TRIANGULATION INTERSECTION STATIONS

- CHIMNEY, RED BRICK HOUSE, GREEN GABLE, 1942, 1943, r. 1943
- CHIMNEY, WHITE HOUSE, RED ROOF, 1942, 1943, r. 1943
- ~~DUTCH GAP LIGHT, 1942, 1943, r. 1943~~ * *James River Light 140*
- ELEVATED WHITE WATER TANK, 1942, 1943, r. 1943 **** *Prob. Lost*
- ~~JONES NECK CUT LIGHT NO. 3, 1942, 1943, r. 1943~~ * *James River Light 141*
- ~~JONES NECK CUT LIGHT NO. 4, 1942, 1943, r. 1943~~ * *James River Light 146*
- ~~LIGHT, TOP N.E. RADIO TOWER, 1942, 1943, r. 1943~~
- ~~LIGHT, TOP S.W. RADIO TOWER, 1942, 1943, r. 1943~~
- *CUPOLA* SOUTH GABLE, CUPOLA, WHITE GRAIN MILL, 1942, 1943, r. 1943
- VARINA WATER TANK, 1942, 1943, r. 1943
- WHITE CHIMNEY (N.E. CHIMNEY WHITE HOUSE), 1942, 1943, r. 1943
- WHITE SILO, GROUP OF WHITE BUILDINGS, 1942, 1943, r. 1943 *

* No check position

**** The Field Inspection Unit furnished the Compilation Office the identification of triangulation station ELEVATED WHITE WATER TANK, also listed WATER TANK, ELEVATED, WHITE, pricked direct on field photograph No. 7631.

This is an intersection station and was established under Project H.T. 226, James River, during the winter 1942-1943. This station could not be held to its geographic position during the running of this radial

26. CONTROL:(Continued)

plot. The directions listed in the field computations, Accession No. G 5488, James River, Hopewell to Richmond, Va. were verified. The description published in Supplement 327, James River, Claremont to Richmond to Gordonville, is not of sufficient detail to ascertain if the tank has been moved to a new location since it was established.

The radially plotted position of this ELEVATED WHITE WATER TANK is located 261.9 meters southwest of the listed geographic position.
See Review Report

UNITED STATES GEOLOGICAL SURVEY MONUMENTED STATIONS:

- RICHMOND B.M. NO. 39, 1932 *USGS*
- RICHMOND B.M. NO. 42, 1943 (also 184) *USGS*
- RICHMOND B.M. NO. 50, 1932 *Lost*
- P.T.S. NO. 56, 1916, r. 1942, 1943
- TT-2T, 1937, r. 1942, 1943. *USGS*
- TT-3T, 1937, r. 1942, 1943 *USGS*

UNITED STATES GEOLOGICAL SURVEY TEMPORARY TRAVERSE STATIONS

MALVERN HILL P.O. $\frac{1}{2}$ MILE S.E. T-ROAD INTERSECTION, 1916, 1918,
r. 1942, 1943
MALVERN HILL P.O. 800 FEET N. INTERSECTION OF ROAD, 1916, 1918
r. 1942, 1943
RUNNIMEDDE STOCK FARM, T-ROAD S.E. AT MAILBOX, 1916, 1918,
r. 1942, 1943
T-ROAD WEST, 25 FEET N. TO THREE MAILBOXES ON E. SIDE OF ROAD,
1916, 1918, r. 1942, 1943.
90 A, 1937, r. 1942, 1943
97 A, 1937, r. 1942, 1943
101+, 1937, r. 1942, 1943
104A, 1937, r. 1942, 1943
107+, 1937, r. 1942, 1943
111A, 1937, r. 1942, 1943
113A, 1937, r. 1942, 1943
117+, 1937, r. 1942, 1943
124A, 1937, r. 1942, 1943
144 A, 1937, r. 1942, 1943
149A, 1937, r. 1942, 1943
152+, 1937, r. 1942, 1943
162A, 1937, r. 1942, 1943
167A, 1937, r. 1942, 1943

See Review Report

The following horizontal control stations fall within the areas adjacent to the north, south, and west limits of this Map Drawing.

UNITED STATES COAST AND GEODETIC SURVEY SECOND ORDER TRIANGULATION STATIONS

CREEK, 1942, 1943, r. 1943
CHAFFIN, 1942, 1943, r. 1943
WOOD (F.I.P. WOO), 1943
• MALVERN, 1932, r. 1943

26. CONTROL: (Continued)

UNITED STATES COAST AND GEODETIC SURVEY TRIANGULATION INTERSECTION STATIONS

JONES NECK LOWER LIGHT, 1943, r.1943 *
WOODEN TOWER, 1942, 1943
SILO NO. 1, WHITE, N. END OF LARGE GRAY BARN, 1942, 1943, r.1943*
SILO NO. 2, at S. CORNER OF GRAY ROOFED BARN, 1942, 1943, r.1943*
SMALL BLACK STACK, 1942, 1943

* No check position

UNITED STATES ENGINEERS STATION

JR 47, r. 1938, 1942, 1943 (Monumented station)

UNITED STATES GEOLOGICAL SURVEY TEMPORARY TRAVERSE STATIONS

14, 1937, r. 1942, 1943	40+, 1937, r. 1942, 1943	171+, 1937, r. 1942, 1943
20A, 1937, r. 1942, 1943	86A, 1937, r. 1942, 1943	278, 1937, r. 1942, 1943
34A, 1937, r. 1942, 1943	136A, 1937, r. 1942, 1943	283A, 1937, r. 1942, 1943

The above listed horizontal control stations, except otherwise noted, both inside and outside the limits of these combined surveys, were used to establish photograph centers, secondary control, and detail points for this Map Drawing.

27. RADIAL PLOT:

The Radial Plot for this Map Drawing is part of the combined Radial Plot for Surveys Nos. T-8089, T-8090, T-8091, T-8094, T-8095, and T-8096, the descriptive report for which, was submitted to the Washington Office on September 1, 1944. Filed in Div. of Photogrammetry - General Files

28. DETAILING

The shoreline and immediate adjacent culture of the part of the James River shown on this Map Drawing has been detailed in accordance with the original instructions dated March 26, 1942, and the Director's letters dated July 15, 1942, and September 30, 1942, pertaining to Project No. CS-283. Filed in Div. of Photogrammetry - Office Files

In a few places, areas such as Jones Neck, Hatcher Island, and a portion of Turkey Island have been fully detailed on this Map Drawing. As these areas contained large marsh and swamp lands, and in some instances waterways or canals, it was deemed advisable to detail all planimetry in these vicinities.

28. DETAILING:(Continued)

The stereoscope was used to verify the shoreline field inspection data furnished the Compilation Office by the Field Inspection Unit. These data were transferred to the office photographs and then detailed on the Map Drawing. In general, the Field Inspection data were satisfactory.

All drainage flowing into the James River and its tributaries has been detailed. Drainage not identified by the Field Inspection Unit has been shown with a light weight, dashed, acid ink line.

The portion of Turkey Island Creek, beyond the limits of small boat navigation which was not identified by the Field Inspection Unit, has been delineated from stereoscopic examination and is also shown on the Map Drawing with a light weight, dashed, acid ink line.

Roads not classified by the Field Inspection Unit, were classified and shown according to the Compiler's interpretation from the nine lens photographs, after comparison was made with available charts and topographic quadrangles.

Tree areas not classified in the field were interpreted by the Compiler from the nine lens photographs. These areas have been detailed and shown with conventional symbols.

All buildings immediately adjacent to the shoreline have been detailed.

Buildings or groups of buildings which were believed to be located at a sufficient elevation so as to be visible from the navigable waters, have also been detailed.

At the head of Fourmile Creek, a pond, namely, Griggs Pond, which is believed to have been formed by the construction of a dam, has been detailed on the Map Drawing. This pond was not identified in the field as it is located beyond the limit of work of the Field Inspection Unit.

A bridge, which did not exist on the date the nine lens photographs were taken, is detailed on this Map Drawing. This bridge is across the James River between Hatcher's Island and the mainland on the west. The Field Inspection Unit sketched this bridge in its proper location on field photograph No. 7631. The bridge was transferred directly from the field photograph to the Map Drawing by orienting the Map Drawing to corresponding common points of detail on the field photograph. An appropriate note relating to this bridge is shown on the Map Drawing.

See Review Report

28. DETAILING: (Continued)

The number of nine lens photographs covering the area of these two surveys were sufficient to adequately compile this Map Drawing. Their scale was in good agreement with the scale of the Map Drawing Projection. The spacing of the photographs in each flight strip provided very good center chamber coverage for the area of this Map Drawing.

A list of abbreviations used on this Map Drawing, accompanied by explanatory notes, has been shown in the right hand margin.

29. SUPPLEMENTAL DATA:

No supplemental data was furnished the Compilation Office for use in detailing this Map Drawing.

30. MEAN HIGH WATER LINE

The conventional full, heavy-weight and light-weight black acid ink lines have been used to differentiate between the Mean High Water Line and the outer limits of marsh bordering the Mean High Water Line, respectively. The light weight line is an indication of the outer limits of low wet land at Mean High Water, and is not considered to be the Mean High Water Line.

In several instances the Field Inspection Unit identified the Mean High Water line on the field photographs with a dashed or broken red ink line.

According to a letter from Lieutenant Commander Henry O. Fortin, dated February 11, 1943, this dashed or broken line indicates that the field inspector could not interpret the shoreline correctly due to shadows, overhang of trees, bluffs, or poor photographs; sometimes a combination of all four.

Where these doubtful areas were indicated on the field photographs, a careful stereoscopic examination was made and the resulting interpretation, supplemented by the Field Inspector's interpretation was then detailed on the Map Drawing with a full, heavy weight line.

31. LOW WATER AND SHOAL LINES

No Mean Low Water Line has been shown on this Map Drawing, and none was indicated by the field inspection data, or was visible on the nine lens photographs.

31. LOW WATER AND SHOAL LINES: (Continued)

Several mud areas, identified by the Field Inspection Unit, are outlined on the Map Drawing with a light weight, dotted, black acid ink line, and labeled "Mud".

Other areas, not identified by the Field Inspection Unit, but shown on the field photographs with a broken green ink line, were interpreted from examination of the nine lens photographs, and are shown on the Map Drawing with a dashed, light weight, acid ink line, and labeled "~~Shoal~~". *Shallow*

32. DETAILS OFFSHORE FROM THE HIGH WATER LINE

Piling areas, pilings across entrances, and remains of barges were identified by the Field Inspection Unit, and are detailed and labeled on this Map Drawing.

Several boulders, offshore from, or at the high water line, in the vicinity of Woodson Rock were indicated on the field photographs by the Field Inspection Unit. These boulders were not visible on the photographs and could not be detailed. The data for these boulders, as furnished by the Field Inspection Unit, has been transferred to the Map Drawing.

One obstruction was detailed on this Map Drawing off the south shore of the James River, west of Meadowville and south of Varina. This obstruction was not identified by the Field Inspection Unit and should be investigated by the Hydrographic Party.

One wreck, identified on field photograph No. 7641, by the Field Inspection Unit, at Point Breemo, has been radially plotted on this Map Drawing. The extent to which it bares has been noted on the Map Drawing, in accordance with the field inspection data.

Position changed on H-7083

33. WHARVES AND SHORELINE STRUCTURES:

Numerous jetties, piers, remains of piers, pilings, a few catwalk remains, wood retaining walls, and a concrete wall were identified by the Field Inspection Unit on the field photographs. These are detailed on the Map Drawing and labeled. No other shoreline structures were visible on the office photographs.

34. LANDMARKS AND AIDS TO NAVIGATION:

The following objects were recommended by the Field Inspection Unit for charting as landmarks. They are:

~~ELEVATED~~ WHITE WATER TANK (see comment under paragraph 26, entitled "CONTROL")
~~LIGHT, TOP~~ N.E. RADIO TOWER (also triangulation station) *See Ch. Letter*

678-44

34. LANDMARKS AND AIDS TO NAVIGATION:(Continued)

Form No. 567 is being submitted for the above recommended landmarks.

The Field Inspection Unit furnished the Compilation Office the identified location, on field photograph No. 7630, for DUTCH GAP LIGHT NO. 2, listed as AIKEN SWAMP CUT LIGHT NO. 2, Fl. R. ev. 5 sec. in the 1944 Light List. This fixed aid to navigation was radially plotted, and comparison was made with its respective position as shown on U.S.C.&G.S. Chart No. 531. It was found that the two positions were not in agreement. Form No. 567 is being submitted for the radially plotted position of this fixed aid to navigation. ~~See Review Report~~ Chart Letter 678(44)
This light is now James River Light 152

Also, falling within the limits of this Map Drawing, are the following fixed aids to navigation which are also triangulation stations. These are shown on the Map Drawing with the triangulation station symbol. They are:

DUTCH GAP LIGHT Fl. W. ev. 5 sec. James River Light 150
JONES NECK CUT LIGHT NO. 3 Fl. W. ev. 5 sec. James River Lt 145
JONES NECK CUT LIGHT NO. 4 Fl. R. ev. 5 sec. James River Lt 146
See Chart Letter 275(46)

The Field Inspection Unit furnished the Compilation Office, and identification of the fixed aid to navigation, Aiken Swamp Cut Light No. 4, Fl. R. ev. 5 sec., pricked direct on field photograph No. 7631. This fixed aid to navigation was radially plotted and falls just west of the western limits of this Map Drawing, and on Map Drawing for Survey No. T-8096. However, this radially plotted position does not agree with the charted position shown on Chart No. 531, issued March 6, 1944. The radially plotted position does agree with the charted position shown on Chart No. 531, issued November 15, 1941. It is believed that this aid to navigation has been moved since the date of the field inspection. Both the radially plotted position and the charted position are shown. The charted position has been shown with a dashed, black acid ink circle.
See Review Report.

35. HYDROGRAPHIC CONTROL:

The Compilation Office was furnished the identification of fifty-seven (57) temporary hydrographic stations, and eleven (11) recoverable topographic stations. These were identified on the 1:10,000 field photographs by numbers, and their descriptions listed in a field sketch book (form 274) by corresponding numbers. These stations were transferred to the office photographs, and radially plotted on the Map Drawing. The numbers and descriptions of these stations have been noted near the station to which they refer, directly on the Map Drawing.

35. HYDROGRAPHIC CONTROL: (Continued)

Form No. 524 is being submitted for the eleven (11) recoverable topographic stations. They are:

- No. 680 - N.W. GABLE ~~UNPAINTED BARN, METAL ROOF~~, 1943
- No. 681 - S.W. GABLE ~~UNPAINTED BARN, GALVANIZED ROOF~~, 1943
- No. 738 - N.W. GABLE ~~UNPAINTED SHINGLED BUILDING~~, 1943
- No. 744 - W. GABLE ~~CURLES NECK MANSION~~, 1943
- No. 755 - W. GABLE ~~SMALL WHITE HOUSE~~, 1943
- No. 756 - S. GABLE ~~UNPAINTED BARN, SHINGLE ROOF~~, 1943
- No. 761 - S. GABLE ~~LONG SHED~~, 1943
- No. 769 - ~~CONCRETE SILO WITH DARK TOP~~, 1943
- No. 794 - S.W. GABLE ~~OF BARN WITH METAL ROOF~~, 1943
- No. 797 - ~~ELEVATED WHITE WATER TANK~~, 1944
- No. 813 - ~~DUTCH GAP LIGHT NO. 2 (also Aiken Swamp Cut Light No. 2)~~
James River Light 152, 1943

36. LANDING FIELDS AND AERONAUTICAL AIDS

The Compilation Office has not been furnished any data for landing fields or aeronautical aids within the limits of this Map Drawing, and none were visible on the nine lens photographs.

37. JUNCTIONS:

- To the north -- No contemporary survey
- To the east -- Map Drawing for Survey No. T-8088 has been combined with Map Drawing for Survey No. T-8089. The small portion of James River and adjacent planimetry, falling within the area of Survey No. T-8088, has been detailed in the right hand margin of Map Drawing for Survey No. T-8089.
- To the south -- A satisfactory junction has been effected with the combined Surveys of this Map Drawing and the Map Drawings for Surveys No. T-8090 and T-8087.
- To the west -- The junction with Map Drawing for Survey No. T-8096 was in satisfactory agreement.

38. GEOGRAPHIC NAMES Approved list filed in Geographic Names Section

As instructed, no geographic name investigation was furnished the Compilation Office. The geographic names shown on this Map Drawing were taken from the following available sources, namely:

- UNITED STATES COAST AND GEODETIC SURVEY CHART NO. 531, dated March 6, 1944.
- UNITED STATES GEOLOGICAL DUTCH GAP, VA. 7½ min. quad. surveyed in 1938
- UNITED STATES COAST PILOT, ATLANTIC COAST, section C, SANDY HOOK
TO CAPE HENRY

38. GEOGRAPHIC NAMES: (Continued)

Both undisputed and disputed Geographic Names are shown on the Map Drawing. In instances where disputed names occurred between the U.S.C.&G.S. Chart and the U.S. Geological Survey Quadrangle, the preference was given to the U.S.C.&G.S. Chart.

A list of the undisputed geographic names and a list of the disputed geographic names are attached to this descriptive report.

39. HORIZONTAL ACCURACY:

The probable error in the relative positions of detail points, the mean high water line, and well defined objects, is believed to be within the limits of satisfactory accuracy.

40. RECOMMENDATIONS FOR FUTURE SURVEYS

This rough draft, shoreline Survey for the Map Drawing of the combined Surveys, Nos. T-8088 and T-8089, is believed to be completed in all details for charting and no other surveys are deemed necessary.
Combined surveys number is T 8089 (T 8088 dropped)

44. COMPARISON WITH EXISTING TOPOGRAPHIC QUADRANGLES

Comparison was made with the U. S. Geological Survey, Dutch Gap, Va., 7½ minute quadrangle, scale 1:24,000 surveyed in 1938, advance unedited edition. The following difference was noted:

On the north shore of the Aiken Swamp - Dutch Gap Cutoff, on Hatcher Island, is an area which is being dredged out. This area is not shown on the U. S. Geological Survey Quadrangle. All other shoreline detail and immediate adjacent planimetry are in good agreement.

45. COMPARISON WITH NAUTICAL CHARTS:

Comparison was made with the U. S. Coast and Geodetic Survey Chart No. 531, scale of 1:20,000, dated March 6, 1944. The following differences were noted:

The dredged out area on ~~Hatcher~~ Island, mentioned in paragraph No. 44, does not appear on the chart.

The large marsh area shown on the chart, on the west shore of the James River, west of Jones Neck, has been detailed on the Map Drawing as an area which is flooded at Mean High-Water. An appropriate note has been shown on the Map Drawing in this area.

A large marsh area in the vicinity of Jones Neck with canals flowing through it is shown on the Map Drawing. The detail in this area as shown on the chart is incomplete.

45. COMPARISON WITH NAUTICAL CHARTS: (Continued)

is not shown on the chart. This creek has been detailed on the Map Drawing beyond the limit of small boat navigation.

Turkey Island Creek, which is not shown on the chart, has been detailed on the Map Drawing, as far as it could be delineated from stereoscopic examination of the photographs. This has been shown as marsh area only on the chart.

One wreck, radially plotted on this Map Drawing, at Point Brema, was identified by the Field Inspection Unit. This wreck is not shown on the chart.

At the north end of Jones Neck, on the Map Drawing, is a radially plotted position of a temporary hydrographic signal, numbered 766, which has been described in field sketch book (form No. 274) as "BOW OF ABANDONED BOAT". This is not charted on chart No. 531.

All other shoreline detail and immediately adjacent planimetry are in good agreement.

Respectfully submitted:
September 18, 1944

Albert C. Rauck, Jr.
Albert C. Rauck, Jr.
Senior Photogrammetric Aid

Compilation and Descriptive
Report, Reviewed by

Henry P. Eichert
Henry P. Eichert
Jr. Photogrammetric Engineer

Compilation of Map Drawing
Supervised by

J. Edward Deal, Jr.
J. Edward Deal, Jr.
Ass't. Photogrammetric Engineer

Approved and Forwarded:
September 19, 1944

Fred. L. Peacock
Fred. L. Peacock
Chief of Party, C. & G. Survey
Officer in Charge
Baltimore Photogrammetric Office

Descriptions of Photo-Hydro Stations
T-8089

- 674 - Tip of patch of tall grass, offshore at H. W.
- 675 - Chimney of red roofed, two story, yellow house
- 676 - Tuft of tall marsh grass, 1 m. in diameter
- 677 - Tuft of tall grass detached from other grass
- 678 - Tip of grass on mud bank on E. side of entrance
to break in marsh.
- 679 - Tip of grass on mud bank on E. side of entrance
to stream.
- 682 - Fifteen foot pole on gravel point at remains of
old pier.
- 684 - E. end of fallen, red beacon
- 705 - S. gable of one story, brown
- 712 - Center of small, grass patch, farthest away from
shore
- 713 - Center of offshore grass patch
- 714 - Center of offshore grass patch
- 715 - Small tuft of grass at edge of L.W., .5m in
diameter.
- 716 - Center of tuft of grass, 1 m. in diameter at edge
of L. W.
- 716 A - Tip of grass on mud bank on N. side of entrance
to small stream.
- 724 - End of jetty, third from W. house on pier
- 725 - Cupola on house with red roof on pier
- 726 - Tip of bank at sharp break downward
- 739 - End of jetty, third N. of 737
- 740 - End of second jetty N of 739
- 741 - End of jetty with lantern on white pole
- 742 - Rounding point of grass on SW side of break in
grass
- 743 - NE corner of old pier, only piling remaining
- 746 - End of longer of two rows of piling
- 747 - Corner of S. side of low place in dock
- 748 - Tip of grass
- 749 - Tip of grass on point
- 750 - Remains of dolphin broken off at H.W.L., one
tall piling left.
- 751 - SW gable of green, boat house
- 752 - Tip of bank on SW side of break
- 753 - Center of grass patch with line bush in middle
- 754 - S End of row of piling
- 757 - End of log, half way across creek, bare 1 ft.
at M.H.W.
- 758 - N. side of entrance to break in grass
- 758 A - End of jetty with 3 ft. cedar on end.
- 759 - End of jetty with 3 ft. cedar in middle
- 760 - End of first jetty N. of canal entrance

T-8089

- 770 - Tip of grass
- 771 - Ten foot delphin on W. corner of pier
- 772 - Eight foot pile on end of jetty
- 773 - End of third jetty W. of 772
- 774 - End of jetty W. of barge with growth of trees on it.
- 776 - Outer end of short jetty
- 777 - Chimney in center of unpainted house with galvanized roof
- 778 - End of abandoned catwalk
- 781 - Tip of gravel bank
- 795 - SW corner of pier
- 796 - Eight foot pile on SW corner of pier
- 798 - Tip of grass on W. side of break
- 799 - N. chimney of two story house with chimney on both ends and shed on back, E. side
- 812 - Tuft of grass in entrance to bight

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

NONFLOATING AIDS OR LANDMARKS FOR CHARTS

TO BE CHARTED

STRIKE OUT ONE

Boston, Massachusetts

May 8

1961

I recommend that the following objects which have *(have not)* been inspected from seaward to determine their value as landmarks be charted on *(deleted)* the charts indicated.

The positions given have been checked after listing by

[illegible]

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

NONFLOATING AIDS OR LANDMARKS FOR CHARTS

TO BE CHARTED
TO BE DELETED

STRIKE OUT ONE

Baltimore, Md.

Sept. 19 61 1961

I recommend that the following objects which have *(have not)* been inspected from seaward to determine their value as landmarks be charted on *(deleted from)* the charts indicated.

The positions given have been checked after listing by

Fred L. Peacock *Chief of Party.*

[illegible]

GEOGRAPHIC NAMES

Undisputed

- ✓ • AIKEN SWAMP ✓
- ✓ • BAILEY'S CREEK (US & B. decision) ✓
- ✓ • CURLES NECK ✓
- ✓ • CURLES NECK ROAD ✓
- ✓ • DEEP BOTTOM ✓
- ✓ • DUTCH GAP ✓
- ✓ • FAIR HILL ✓
- ✓ • FARRAR ISLAND ✓
- ✓ • FORT BRADY ✓
- ✓ • FOURMILE CREEK ✓
- ✓ • GRIGGS POND ✓
- ✓ • HATCHER ISLAND ✓
- ✓ • Harall ✓
- ✓ • JAMES RIVER ✓

- ✓ • JONES NECK ✓
- ✓ • Kingsland Road ✓
- ✓ • MALVERN HILL ✓
- ✓ • MEADOWVILLE ✓
- ✓ • PICKETTS WHARF ✓
- ✓ • POINT BREMO ✓
- ✓ • PRESQUE ISLE SWAMP ✓
- ✓ • ROUNDABOUT CREEK ✓
- ✓ • Richmond Yacht Basin ✓
- ✓ • TURKEY ISLAND ✓
- ✓ • TURKEY ISLAND BEND ✓
- ✓ • TURKEY ISLAND CREEK ✓
- ✓ • VARINA ROAD ✓
- ✓ • WOODSON ROCK ✓
- ✓ • Va. No. 5. ✓

Names preceded by • are
approved 12/10/48 - L. Heck

GEOGRAPHIC NAMES

Disputed

U.S.C. & G.S. Chart

U.S.G.S. Quadrangle

✓ 1. AIKEN SWAMP - DUTCH GAP CUTOFF ✓

DUTCH GAP CHANNEL

✓ 2. CURLES (as on chart 531) ✓

CURLES NECK PLANTATION

✓ 3. JONES NECK CUTOFF ✓

MEADOWVILLE CHANNEL

✓ 4. VARINA ✓

AIKEN HOUSE

✓ 1. Curles Neck Plantation ✓
(as on chart 531)

Division of Photogrammetry
Review Report of
Shoreline Map Manuscript T-8089

Subject numbers not used in this report have been adequately covered in other parts of the descriptive report.

26 - Control.- The following triangulation stations were removed from the map manuscript. They were reported lost.

Dutch, 1932

Richmond BM No. 50(USGS), 1932

All unmarked USGS temporary traverse stations were deleted.

The triangulation station, "Elevated, White Water Tank, 1942" is apparently lost. A tank in the same vicinity with the same description has been located by the radial plot and the position obtained has been verified by the hydrographic party in 1946. See Chart Letter 678(44) for its position.

The names of lights along the James River have been changed. The Light List name has been shown on the map manuscript followed by the triangulation station name in parenthesis.

28 - Detailing.- The symbolization of several areas of "grass in water" and mud has been changed to conform with recent instructions.

The symbols for jetties should be changed to standard specifications by the smooth draftsman.

A bridge that had been sketched on a photograph by the field inspector and shown on the map manuscript with a dashed line, has been deleted. The correct position for this bridge is shown on H-7083. The bridge clearance note has been left on the map manuscript with an arrow to its approximate position. *Not on registered copy.*

34 - Landmarks and Aids to Navigation.- Aiken Swamp Cut Light 4 was renamed James River Light 154 and the position changed. See Chart Letter 275(46) for the new position. The radially plotted position and the position transferred from the old Chart 531 have been removed from the map manuscript.

Copies of Chart Letters 275(46) and 678(44) were prepared and made a part of the descriptive report.

Reviewed by:

Charles Hener
C. Hener
12-21-48

S. V. Griffith
S.V. Griffith R.N.M.
Chief, Review Section

Approved by:

B. J. Jones 7/50
B. J. Jones, Econ. Asst.
Chief, Div. of Photogrammetry

H. B. Munster
H. B. Munster
Chief, Nautical Chart Search
Division of Charts

O. S. Reading
O. S. Reading
Chief, Div. of Photogrammetry

W. M. Acafe
W. M. Acafe
Chief, Div. of Coastal Surveys